

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-7-12	109	CHAPEL ST	B	REL	REL	CH	ROM	1893	na	na	na	NH	M	B & S	N	CL	CG & H	A	N	na	INT	REP	F	INT	INT	Y	N
56.17-7-15	113	CHAPEL ST	B	SFR	DOM	SD	QA	c1890	2	O	na	NH	WF	WC	N	CL	CG	SSM	N	N	INT	INT	F	INT	INT	Y	N
56.17-8-3	114	CHAPEL ST	B	MFR	DOM	SD	QA	c1890	2	O	N	N	WF	WC	CC	CL	GAM	A	N	OR	INT	INT	F	INT	INT	Y	N
56.17-7-14	115	CHAPEL ST	B	SFR	DOM	SD	IT	c1870	2	O	N	N	WF	WC	N	CL	M	S	N	N	INT	INT	F	INT	INT	Y	N
56.17-8-4	116	CHAPEL ST	B	MFR	DOM	SD	GO	c1870	2	TH	RE-1	N	WF	WC	CC	CL	FG	SSM	N	N	REP	REP	F & R	INT	INT	Y	N
56.17-8-5	118	CHAPEL ST	B	MFR	DOM	SD	IT	c1870	2	O	SE-2 RE-1	N	WF	WC	VS	CL	FL	U	N	N	REP	INT	F	INT	INT	Y	N
56.17-7-13	119	CHAPEL ST	B	MFR	DOM	SD	CR	c1890	2	O	N	N	M	B	N	CL	H	S	N	OR	INT	INT	F	INT	INT	Y	N
56.17-8-6	120	CHAPEL ST	B	SFR	DOM	SD	A4	c1910	2	SQ	RE-1	N	WF	WC	VS	CL	H	A	N	OR	REP	REP	F	ENC	INT	Y	N
56.17-8-7	122	CHAPEL ST	B	SFR	DOM	SD	GO	c1870	2	TH	N	NH	WF	WC	N	CL - alt	FG	A	N	N	ALT	REP	F	ENC	ALT	Y	N
56.17-7-12	-	CHAPEL ST	SI	VAC	LAN	UNO																				N	

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Methodist Church; Roman arches; curved corners on tower; wood shingles on tower & gable ends; raised basement w/limestone foundation; mid-20th cent. rear/west wing addition	N							
Decorative verge bds & brackets on gables; exposed carved rafters; shutters; scroll sawn brackets on ft porch; dec. siding on gable ends & side bay windows; stained glass transom front window; Barn has dec. stick work on 2nd floor; novelty siding below	B	Y	N	ALT	Y	N	shed addition to E side to accom. Double garage door; stick work on 2nd fl. & novelty siding below	Mature decid tree on front lawn
Pedimented dormer gables & front porch; side box bay w/bracket supports; 2-story front bay; numerous stained glass windows; round attic window; sq. columns 2-paneled bases on front porch; original chimneys w/limestone caps & bases	N						This building has no barn or garage, altho next door neighbor to west has 2 substantial barns, 1 of which may be original to this property	
Decorative/scroll sawn bracketed cornice-2 sizes of brackets; door & window surrounds w/dec. headers on 2nd floor windows & applied wood moldings; eye brow attic "windows" (shuttered vents) in mansard roof; Corinthian columns on porch, scroll sawn porch skirting; corner boards w/braces; west 1/2 of porch glazed	B	N	N	INT	Y	N	FG roof; hay door & attic window; garage doors all intact	
Turned columns & scroll sawn brackets on front porch; window surrounds; verge boards w/scroll ends; spindled porch frieze NOTE: appears to have many of its original decorative elements removed or covered; probably had a DGEVS at one time; porch balustrade has been repaired	N							
Bracketed cornice; Doric columns on porch; NOTES: some porch ballustrades missing	B	N	N	INT	Y	N	WF/WN siding; 1-story addition to west	
Raised basement; limestone window headers & lintels; Roman columns; modillions on wide overhanging eaves; fanlight/window in W side bay; pedimented gable on 2-story bay windows on front & side; leaded glass & stained glass windows; Roman arched attic window; limestone caps on stepped chimney	G	N	N	INT	Y	N	small early 20th century garage; WF/WC	
Hipped dormer; porch was enclosed early if not originally	G	Y	N	INT	Y	N		White picket fence on 3 sides
Simple proposition of orig. bldg still in evidence. NOTE: front porch has been enclosed, brick piers added; attic window infilled	SH							White picket fence on 3 sides
Vacant lot owned by the Methodist Church; was the site of a 2-story house & barn (1904 & 1927 Sanborns); unimproved; portion w/in historic district used for parking	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-7-11	125	CHAPEL ST	B	MFR	DOM	SD	SE	c1880	1	O	RE-1s	NH	WF	WC	N	CL	M	WS	N	OR	INT	INT	FWS	INT	INT	Y	N
ROW	-	CLINTON CIR East of N. GRAND	ST	BRI	TRA	RD	CC	c1920	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na		
68.5-3-54	104	CLINTON CIR	B	SFR	DOM	SD	TR	c1925	2	O	N	N	WF	WS BB & STU	N	CL	FG	A	N	OR	INT	INT	na	na	INT	Y	N
68.5-3-55	107	CLINTON CIR	B	SFR	DOM	SD	RA	c1960	1	O	N	N	WF	COM	N	CB	G	A	N	N	INT	INT	F	INT	INT	N	N
68.5-3-53	108	CLINTON CIR	B	SFR	DOM	SD	DC	c1930	2	CP	N	N	WF	WC & WS	N	CL	FGAM	A	N	N	INT	INT	na	na	INT	Y	N
68.5-3-52	110	CLINTON CIR	B	SFR	DOM	SD	TR	c1925	2	O	N	N	WF	WC	MS	CL	CG	A	N	OR	INT	INT	na	na	INT	Y	N
68.5-3-51	112	CLINTON CIR	B	SFR	DOM	SD	CLR	c1927	2	CP	N	N	WF	WC	MS	RFC	G	S	N	OR	INT	INT	F	ENC	INT	Y	N
68.5-3-50	114	CLINTON CIR	B	SFR	DOM	SD	BUN	c1920	1	O	N	N	WF	WC & WS	MS-1st	CL	G	A	N	OR	INT	INT	F	INT	INT	Y	N
68.5-3-49	116	CLINTON CIR	B	SFR	DOM	SD	DC	c1925	2	O	SE-1 E	N	WF	WC	MS	CL	FG	A	N	N	REP	INT	F	INT	INT	Y	N
68.5-3-48	118	CLINTON CIR	B	SFR	DOM	SD	CC	c1925	2	O	SE-1- W	N	WF	WC	MS	CL	G	A	N	AD	MIX	INT	na	na	ALT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Window & door surrounds; broken-eave dormers; mansard roof w/fish-scale shingles; arched headers over 1st floor windows; scroll sawn dec. elements; front bay incorp. front porch; bracketed eave/cornice; turned columns; applied wood ornaments on porch eaves; corner boards flared at top	B	N	N	INT	Y	Y	WF/wood plank siding; hay door	
Stone & Concrete Bridge; cobblestone piers w/concrete caps; & horizontal wood railings; sidewalks both sides; not on 1904 Sanborn; on 1927 Sanborn	N							
Arched doorway & windows; 1-story bay window on front façade; half timber w/stucco gable end; battered walls on 1st floor; metal edge on roof	G	Y	N	INT	Y	N	Multi-paned attic window; half timber detailing; detached garage is of later date per Sanb maps	
Infill building; partially resided with wood novelty siding; attached garage	N							
Pentice at 1st floor w/canopy extension over front door; false gambrel pentice on 2nd story; false "hay door" on 2nd floor west side; paneled eaves; beaded joints on found.; orig. house on lot appears to have been moved to next lot west from Sanborn maps	G	Y	N	INT	Y	N	Jerkin Head FG roof; WF, WC & WS	
Eyebrow detail over front door; front chimney; sloped roof to 1st floor sun porch NOTE: this bldg appears to have been moved to this location from next lot east per Sanborn maps	G	Y	N	INT	Y	N	WF; WC; hipped roof w/hipped dormer; this garage is attached to the neighboring garage to the east with a small double door shed; garage appears to predate house on the property (c1927 per Sanborn map)	Brick steps; brick piers flank front entrance; cobbled front walkway
Square pilasters flanking front door; rock-face molded concrete block piers on front porch; metal edge on slate roof; painted foundation	G	N	N	INT	Y	N	WF; WC; hipped roof with hipped dormer; attached to neighboring garage to east	
Bracketed gable eaves on dormer & end gables; square columns on brick piers of front porch; exposed & slightly curved/carved rafters; window & door surrounds; vertical muntins in upper sashes of windows; intact chimney	G	Y	N	INT	Y	N	Dormer with vertical muntins in upper sash	
False gambrel pentice on 2nd floor; pentice at 1st floor; intact chimney; bow window on front façade; Doric columns on small front porch; pedimented porch; NOTE some orig. detailing appears to have been lost due to residing	G	N	N	na	N	N	WF; MC front gable double garage appears to date to late 20th century	
Appears to be a greatly altered Craftsman's style house; dormer may be enlarged or new; bracketed canopy over front door indicates type of detailing that has been removed & covered over; front bay window added	G	Y	N	INT	Y	N	Garage does not appear on 1927 Sanborn map but is early w/2 single stall doors 1orig & one replaced w/overhead door	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-66	120	CLINTON CIR	B	SFR	DOM	SD	CLR	c1940	2	CP	SE-1-S & RE	N	WF	WC	N	RFC	G	SSM	N	N	INT	INT	S	INT	INT	Y	N
68.5-3-65	122	CLINTON CIR	B	SFR	DOM	SD	TR	c1940	2	O	SE-1 E&W	N	WF	WC	N	RFC	CG	A	N	N	INT	INT	na	na	INT	Y	N
68.5-3-64	124	CLINTON CIR	B	SFR	DOM	SD	CLR	c1930	2	CP	RE-1	N	WF	WC	N	PC	H	A	N	N	INT	INT	F	INT	INT	Y	N
68.5-3-63	126	CLINTON CIR	B	SFR	DOM	SD	DC	c1930	2	CP	SE-1 NW & SE	H	WF	WC	MS - 2nd floor	CL	GAM	A	N	OR	INT	INT	F	INT	INT	Y	N
68.5-3-62	128	CLINTON CIR	B	SFR	DOM	SD	RA	c1946	1	RA	N	N	M	B	N	CB	G	A	N	N	INT	INT	F	INT	INT	N	N
68.5-3-61	130	CLINTON CIR	B	SFR	DOM	SD	CC	c1920	1-1/2	O	SE-1	N	WF	WC	VS	CL	G	A	N	OR	INT	INT	na	na	INT	Y	N
68.5-3-60	132	CLINTON CIR	B	SFR	DOM	SD	A4	c1915	2	O	N	N	WF	WC	N	CL	H	A	N	OR	INT	INT	F	ENC	INT	Y	N
68.5-3-59	134	CLINTON CIR	B	SFR	DOM	SD	A4	c1920	2	O	N	N	WF	WC	PS & VC	CL	H	A	N	N	MIX	ALT	F	A	ALT	Y	N
68.5-3-58	136	CLINTON CIR	B	SFR	DOM	SD	TR	c1940	2	O	SE-1 E & W	NH	WF	WC	N	PC w/B	CG	A	N	OR	INT	R	na	na	INT	Y	N
68.5-3-57	140	CLINTON CIR	B	SFR	DOM	SD	A4	c1920	2	O	N	N	WF	WC	MC	CL	H	SSM	N	OR	REP	INT	F	REP	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Curved pediment on front door surround w/dentils; fluted pilasters flanking front door; wood shutters; square columns on side porch	N							
Arched front door; fanlight over front door; steeply pitched roofs; front entry bay; massive brick chimney on front façade; 1-story garage ell appears orig.	N							
Fluted Doric Columns on small front porch; wide corner pilasters; bow window flanking front door; blinds with 's' hooks; pedimented roof detail over front entry w/dentils; rear ell consists of attached garage, lean-to & breezeway to house; 2 massive endwall chimneys	N							
Pedimented front porch w/Doric columns; shutters; large shed-roofed dormer; single stall garage addition off SE side & 1-story sun porch addition appear to be made by 1945 (Sanborn map)	N							
Post WWII housing; slight roof projection over front entry creates porch; sq. columns; orig chimney	G	N	N	INT	Y	N	Garage is earlier than house, blt betw. 1927 & 1945 per Sanborn maps; has cobblestone façade w/cblstn chimney; pentice; Jerkin Head FG roof; attic window; 1 garage door orig.; 1 replaced w/overhead door	
Jerkin Head gable roof; bracketed front canopy over entry; blinds on 1st floor windows; 6-over-1 sash windows; broken-eave dormers; large intact chimney	G	Y	N	ALT	Y	N	Has Jerkin Head FG roof; overhead doors have been installed	
Hipped dormer; large intact chimney; canopy over side entrance door	G	Y	N	INT	Y	N	Single stall garage probably dates to 1915 (on 1927 Sanborn); OH door installed	
Fluted pilasters on door surround; many details do not appear to be original to this A4/Craftsman type house: dentils on window & door headers; ; turned columns & small decorative braces on front porch; full front porch shown on Sanborn has been removed & replaced with small entry porch; front 1st floor windows replaced earlier ones; orig. chimney covered w/perma-stone	G	Y	N	INT	Y	N	Small one-stall garage probably dates to house with its hipped roof; o.h. door installed	
Steeply pitched roofs; fanlight w/dentils over front door; exposed rafters on front eaves; 1-story addition off east side is later than 1945	G	Y	N	INT	Y	N	FG; WF/WC; o.h. door installed; appears on 1945 Sanborn map; large open lot area appears to be an undeveloped ROW	
Bay window w/brackets below on No. side; blinds on windows; hipped dormer	G	Y	N	INT	Y	N	WF; WC; 2-stall; hipped roof with hipped dormer; o.h. door installed; lean-to addition off So. side	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-56	142	CLINTON CIR	B	SFR	DOM	SD	RA	c1970	1	L	N	N	WF	COM	N	PC	FG	A	N	N	INT	INT	na	na	INT	N	N
68.5-3-67	PARK	CLINTON CIR CENTER	SI & ST	REC	R/C	REC	CC	c1920	na	na	na	na	M & WF	na	na	na	na	na	na	na	na	na	na	na	INT	Y	N
68.6-2-5	105	DIVISION ST	B	MFR	C/T	SPE	U	c1890	2	O	N	H	WF	B & WC	AS & WS	CL	G & FL	U	N	N	MIX	REP	na	na	ALT	Y	Y
68.6-2-4	-	DIVISION ST	SI	VAC	C/T	SPE	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	ALT	N	na
68.6-1-12	106	DIVISION ST	B	C	C/T	SPE	CR	c1880	2	O	RE	NH	WF	PM	W & STU	CL	FL	U	N	N	ALT	ALT	na	na	ALT	Y	N
68.6-1-13	108	DIVISION ST	B	C	C/T	SPE	CR	c1880 & c1895	2	O	RE	H	M	B	N	CL	FL	U	N	N	INT	REP	na	na	INT	Y	N
68.6-2-3	109	DIVISION ST	B	C & R	DOM	SD	IT	c1885	2	O	RE	H	WF	WC	WC & AS	CL	FL	U	N	N	MIX	MIX	F	REM	ALT	Y	
68.6-2-2	111	DIVISION ST	B	MFR	DOM	MD	IT	c1895	2	O	RE-1	H & NH	WF	WC	N	U	S	A	N	N	MIX	ALT	F	REM	ALT	Y	Y
68.6-1-14	PKG	DIVISION ST	ST	PKG	DOM	HOT	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	ALT	N	na

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Ranch infill house	N							
Cobblestone & wood pergola park structure; formal plantings of coniferous trees along the road edge with open space around the pergola; located at center of the subdivision development	N							
Italianate brackets at cornice of bldg. on right; paneled recess on left door of gable bldg; NOTE: Two buildings have been combined; neither show up on 1887 Sanborn maps. Poor maintenance & unsympathetic remodelings.	N							
Vacant lot; site of 2-story wood frame "store" as labeled on the 1927 Sanborn map	N							
1882 Sanborn map indicates this was a Cigar Factory; pressed sheet metal on 2nd story façade w/4 sets of double pilasters/corinthian columns (mfg. by Mesker Brothers); raised parapet; floral panels NOTE: 1st floor completely altered with mid-20th century remodeling with wood siding; contemporary bldg to north (indicated on 1882 Sanborn map shown as a confectionery) has been either demolished & replaced with 1-story side ell or reduced to the present dimensions of this ell	N							
Two bldgs. one to South is on 1883 bird's-eye view; bldg to north is blt after 1892; intact storefronts; arched brick headers over 2nd floor windows (so. 4) & limestone lintels; bldgs unified w/1 dec. metal cornice w/urn finials & floral mold; brick has been painted	N							
Bldg. is shown in present configuration on 1887 Sanborn map; may also be shown on 1883 birdseye view; Italianate brackets & cornice remain on south side of building; enclosed exterior stair addition on north side (20th century); some orig. windows on 2nd floor; chimney added to south side	B	N	N	ALT	Y	Y	Barn is attached to streetfront bldg via 1- & 2-story additions to rear	Stone & tile cladding on front of current bar uses stone to match small retaining walls dating to mid-20th century
Dentiled cornice on 1st floor bay window; dentiled cornice on north facade; appears to have been blt as a 2-family dwelling; foundation may be wood cribbing; mid- to late- 20th century additions include exterior enclosed stairway on south facade, open exterior stairway to 2nd fl. along north facade, & 2nd story rear addition over 1st floor rear ell; does not appear on 1892 Sanborn map NOTE: brackets at cornice have been removed along with front porch along entire front of bldg.	N							
Village parking lot on the site of the former "Commercial Hotel" shown on 1883 birdseye view of Cobleskill & 1887, 1892, 1904 & 1927 Sanborn maps	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.6-2-1	-	DIVISION ST	SI	VAC	C/T	SPE	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	N	na
ROW	-	ELM ST	ST	BRI	TRA	RD	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	ALT	Y	N
68.5-3-9	105	ELM ST	B	SFR	DOM	SD	SE	1863	1	O	RE	N	WF	WC	N	CL	M	WS or S	Y	OR	INT	INT	F	INT	INT	Y	N
56.17-6-10	106	ELM ST	B	C	C/T	OFF	CR	c1950	1	O	RE	NH	M	B	N	CB	H	A	N	N	INT	INT	na	na	INT	Y	N
68.5-3-8	107	ELM ST	B	SFR	DOM	SD	QA	c1890	2	O	N	N	WF	WC	N	CL	FG w/ CGAM	S	N	N	INT	INT	FWS	INT	INT	Y	N
68.5-3-7	111	ELM ST	B	SFR	DOM	SD	QA	c1885	2	O	RE	N	WF	WC	VS	CL	GAM w/FG	S & SSM	N	OR	INT	INT	F	INT	INT	Y	N
56.17-6-11	112	ELM ST	B	SFR	DOM	SD	QA	c1890	2	O	N	H	WF	WC	N	CL	H	S	N	N	INT	INT	FWS	INT	INT	Y	N
68.5-3-7	113	ELM ST	B	SFR	DOM	MD	QA	c1895	2	O	RE	N	WF	WC or WS - ?	VS	C;	H	S & SSM	N	OR	INT	INT	F F	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Vacant lot; 1904 Sanborn shows 1 bldg w/2 stores, "Cigar & Millly"	N							
Elm St. bridge across Mill Creek just west of North Grand St.; appears to be in place on 1883 Birdseye; on 1927 Sanborn; functional design w/reinforced poured concrete railing w/out ornamentation w/steel barriers adjoining	N							
James & Amelia Borst House (he was a carriage trimmer); original arched front doors; winged headers on dormers; ornate arched headers on 1st floor windows w/blinds; scroll sawn crown decoration on front tower window header; quoined corners; cornice on tower has scroll sawn dec. pediments w/finials (these may be DGEVSS); dec. wood shingles on mansard roof (painted); dec. pierced cornice boards NOTE: porches have been remodeled per 1927 photo	G	N	N	INT	Y	N	Hipped roof garage is c1915; WF, WC. Although it doesn't match the much earlier house in style, it is complementary & appears to be relatively intact except for o.h. door	
6-over-6 sash windows; Greek surround & transom over entrance doors; paneled entrance doors w/multi-paned windows; extensive rear ell/wing addition dating to late 20th century	N							
Paired Doric columns on wrap-around porch (triple @ corners); intact railing w/turned balustrades; gambrel roof on projecting side bays; ornate decorative brackets on overhanging attic level; garland swag decorations on some 1st floor window headers; Greek temple front gable w/fish scale shingles & dentiled cornices; diamond-paned windows; transoms in front windows	B	Y	N	ALT	Y	N	Large WF/WC cross gambrel carriage house of same vintage as house; probably contained caretaker's residence; slate roof; dentils @ cornice; gable over entrance; NOTE: some alterations - o.h. doors; small porch & windows added	
Tower dormer w/dormers; colored glass in tower dormer windows; fluted Doric columns & porch railing intact; 2-story side bay window on east façade NOTE: dec. detailing has been covered with vinyl siding	B	Y	N	INT	Y	N	Large WF/WC 2-story gable barn with chimney & second story windows; o.h. doors installed; SSM & partial slate roof	
Front & side gables over projecting bays (side is 2-story bay window); dec. gable end w/fish scale shingles & battens; bracketed eaves & scroll sawn skirting on wrap-around porch; west side of porch glazed; stained galss transom in front window; rear 1-story lean-to probably a early 20th century addition	B	N	N	INT	Y	N	WF/WC 2-story gable barn with sliding doors & entrance door still intact; windows added to 2nd story	
This house is on the same lot as 111 Elm St.; Doric columns on front porches match those of that house; blt as a duplex; 2 oval windows w/stained glass on front façade NOTE: dec. details have been covered over or lost due to vinyl siding; porch railings have been covered; hipped roof may have been cut down	-						See 111 Elm Street, which shares the barn with that house	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-6	115-117	ELM ST	B	MFR	DOM	SD	QA	c1890	2	O	RE	N	WF	WN & WS	N	CL	H	S	Y	N	INT	INT	F & S	INT	INT	Y	N
56.17-6-12	116-118	ELM ST	B	MFR	DOM	SD	QA	c1885	2	O	N	H & NH	M	B	N	CL	H	S & A	N	N	INT	INT	FWS	INT	INT	Y	N
68.5-3-5	119	ELM ST	B	SFR	DOM	SD	CA	c1945	1	O	SE	N	M	B	N	PC	G	A	N	N	INT	INT	na	na	INT	N	N
56.17-6-13	120	ELM ST	B	SFR	DOM	SD	GO	c1880	1- 1/2	UPW	N	N	WF	WC & BB	N	CL	CG	A	N	OR	INT	INT	F & R	INT	INT	Y	N
56.17-6-13	122	ELM ST	B	MFR	DOM	SS	N	c1880	2	na	N	N	WF	WC	VS	CL	FG	A	N	N	ALT	ALT	N	na	ALT	Y	N
56.17-6-14	124	ELM ST	B	MFR	DOM	SD	IT	c1885	2	O	RE & SE	N	WF	WC & WS	VS	CL	FL	A	N	N	INT	INT	FWS & R	INT	ALT	Y	Y

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Paneled double front doors; dec. exposed rafters; banding; various shaped slate roof tiles; projecting front & side bays w/gable ends dec. w/shingles; bas relief carved panel on porch pediment; scroll sawn paneled balustrade & turned columns on porches; tall staircase window on west side; 2-story porch on east side; stick work; 1-1/2 story rear ell NOTE: This house is assigned two street #s because barn has been converted to a dwelling	B	N	N	ALT	Y	N	Owner states that the Barn/ Carriage House was blt in 1903; WF/WC; hip roof w/slate shingles; eyebrow window; cupola w/ hipped tower roof & finial; hipped dormer window NOTE: although its condition is altered w/ addition of windows & renovated siding, it contributes to the district due to maintaining form	
Known as the "Rua Home"; blt by Warner farmer named Tingue; imported Belgium polished brick used on exterior; Double Doric columns on paneled pedestals & intact railing on wrap-around porch & porte-cochere w/CL base; CL headers on windows & doors; curved front 2-story bay on west façade; Venetian window & stick work in front projecting cross-gable bay; engaged 3-story engaged octogonal tower w/modillions at front SE corner over curved porch roof; larger rear 2-story octog. tower; copper finials on towers & copper roof edging; not on 1883 Birdseye [property not shown on 1887 or 1892 Sanborns; on 1904 Sanborn; NOTE: 2 rear 1-story porch additions date to early & late 20th century	B	Y	Y	INT	Y	N	WF/WC 2-story; Hay door intact; attic windows w/blinds; decorated gable end with various shaped shingles; paneled banding; DGEVS w/pendants; 2 o.h. doors installed	
Cape Cod style post WWII house; window blinds; end chimney; paneled door; 2-stall attached garage	N							Large front lawn due to setback of house which is out of character with rest of streetscape
Ornately decorated with board & batton in gable ends & over attic portion of wall; window & door surrounds/ window headers; broken eave dormers w/Jerkin Heads; scroll sawn banding; dentiled & bracketed porch & bay window cornices; unique scroll sawn braces on porch columns; paneled porch railing; orig. double front entry doors NOTE: stair railing replaced w/iron	N						Barn for this property has been converted to a multi-family residence - see 122 Elm Street	
NOTE: This was the original barn for 120 Elm Street (c1880) that has been adapted for residential use in the late 20th century; no original siding or ornamentation remains, however its location & overall form make it contributing to the district	N							
Curved wrap around front porch with modillions; Roman columns; Scroll sawn decor on rear porch; 1-story bay window on west façade NOTE: many decorative details (such as brackets) removed & covered when vinyl siding installed; endangered due to lack of maintenance	B	Y	N	INT	Y	Y	Fully intact WF, WC barn with orig. doors & windows; endangered due to lack of maintenance	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-4	125	ELM ST	B	SFR	DOM	SD	GO	c1875	2	TH	RE	N	WF	WC	N	CL	FG	S	N	N	INT	INT	F & S	INT	INT	Y	N
56.17-6-15	126	ELM ST	B	SFR	DOM	SD	QA	c1885	2	O	N	N	WF	WC	N	CL	CG	A & SSM	Y	OR	INT	INT	F	INT	INT	Y	N
68.5-3-3	127	ELM ST	B	SFR	DOM	SD	SE	c1880	2	TH	RE	N	WF	WC	N	CL	M	S or WS	N	N	INT	INT	F & S	INT	INT	Y	N
56.17-6-1	128	ELM ST	B	SFR	DOM	SD	GO	c1890	2	UPW	N	H	WF	WC	N	CL	H	A & SSM	Y	N	INT	INT	F	ALT	INT	Y	N
56.17-6-1	-	ELM ST @WASHINGTON AVE	B	REL	REL	CH	GO	1894	na	N	RE	N	M & WF	B & WS	N	CL	G	S	N	N	INT	INT	na	na	INT	Y	N
68.5-3-2	129	ELM ST	B	MFR	DOM	MD	QA	c1890	2	O	N	N	WF	WC	N	CL	H	S	Y	OR	INT	INT	F	INT	INT	Y	N
68.5-3-1	131	ELM ST	B	SFR	DOM	SD	A4	c1910	2	O	SE	N	WF	WC	VS	CL	H	A	N	OR	MIX	INT	F	INT	INT	Y	N
56.17-1-1	134	ELM ST	B	MFR	DOM	SD	QA	c1900	2	O	RE	NH	WF	WC & WS	MS	CL	FG	S	N	A	ALT	U	FWS & R	ALT	ALT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Scroll sawn braces & eave decor., orig. railings on front porch; window surrounds; bay window w/brackets & panels on east façade; arched attic window NOTE: owners state the title shows property sold in 1884; appears to be on 1883 birdseye view	G	N	N	INT	Y	N	2-stall gar.; hip roof; WF/WN siding; sliding garage doors & window intact; c 1920	
Dentiled cornices on 2 front porches & window headers; garland & subburst details in gable ends; "Lock Tab" asphalt shingles w/terra cotta cap; stick work on west side gable; hipped dormer over east front porch	G	N	N	INT	Y	N	WF; WC 2-stall garage with 2 overhead doors installed; c1920	
Highly decor front porch w/dentils, braces, pendants, sawtooth molding; window blinds; cornice w/horiz. windows & highly decor. attic window surrounds; false windows w/blinds on tower; 1-story box bay; rear 1-story ell; appears to be on 1883 birdseye view	G	N	N	INT	Y	N	2-stall gar; front gable, WF/WN siding; sliding garage doors intact; c1920	Manicured shrubs in front
Banding; decor. shingles & vent screens in gable ends; chimney added	G	N	N	INT	N	N	WF; WC 2-stall; dates to late 20th century	
St. Vincent De Paul Catholic Church; this church replaced the orig. 1870 Catholic church on this site; Gothic arched stained glass windows; Gothic arched entrance door; lozange stained glass window in rear gable end; pyramidal spire atop square bell tower w/pinnacles; decor. shingles, round panel and arched on bell tower; colored mortar used to match brick NOTE: side entrance vestibules on east & west facades date to mid-20th century	O	N	na	na	N	N	20th century brick/masonry educational & accessory buildings occupy the rear portion of the property	
5 DGEVS; scroll sawn brackets w/pendants on corners of front & side bay windows; Doric columns on porch; intact railing & skirting; curved battens on gable ends & in porch pediment; multiple projecting bays; colored mortar in CL foundation	SH	N	N	na	N	N	very small shed; barn does not appear to be connected with this property	
Pedimented front porch gable roof; 12-over-one sashes on upper story windows; side ell is a 1-story sunroom w/16-over-1 sash windows	G	Y	N	ALT	Y	N	2-stall garage; WF orig. WC now VC; o.h. doors installed	
Scroll sawn porch skirting & pediment decor.; bracketed projecting gable; decor. battens & banding on front gable end; blt-in bench on side porch; window blinds; front partially enclosed; railing probably altered NOTE shed dormers to both sides of gable roof; exterior enclosed stairway to upper floors on west side added & 2-stall garage all added in 20th century	N							bluestone walkway

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-2-16	135	ELM ST	B	SFR	DOM	SD	QA	c1890	2	O	N	N	WF	WC	N	CL	H	SSM	N	N	INT	INT	FWS	INT	INT	Y	N
56.17-1-3	136	ELM ST	B	MFR	DOM	SD	QA	c1890	2	O	RE	NH	WF	WC	VS	CL	H	A	N	N	INT	INT	F	ALT	INT	Y	N
68.5-2-15	137	ELM ST	B	SFR	DOM	SD	CR	c1925	2	CP	RE - 1	H	WF	WC	VS	U	G	A	N	OR	MIX	INT	F & S	INT	INT	Y	N
56.17-1-4	138	ELM ST	B	SFR	DOM	SD	QA	c1890	2	O	RE	N	WF	WC	N	CL	CG	A	Y	N	INT	INT	FWS	INT	INT	Y	N
68.5-2-14	139	ELM ST	B	SFR	DOM	SD	QA	c1860	2	O	RE-1	N	WF	WC	VS	CL	H	A	N	N	INT	INT	FWS	INT	INT	Y	N
56.17-1-5	142	ELM ST	B	SFR	DOM	SD	DC	c1925	2	SP	SE-1	NH	WF	WC & WS	N	CL	FGAM	A & WS	N	N	INT	INT	F & R	INT	INT	Y	N
68.5-2-13	143	ELM ST	B	SFR	DOM	SD	CR	c1915	2	O	N	H	WF	COM	MS	PC	FG	A	N	N	REP	?	F	ALT	INT	Y	N
56.17-1-6	144	ELM ST	B	SFR	DOM	SD	A4	c1920	2	SQ	N	N	WF	WC	N	PC	H	A	N	OR	REP	INT	F & S	INT	INT	Y	N
68.5-2-12	145	ELM ST	B	SFR	DOM	SD	CR	c1915	2	O	N	H	WF	WC	partially-VS	CL	FG	S	N	OR	MIX	INT	F	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Curved wrap-around porch with Roman columns & modillions on eaves; 2-story bay windows on front, east side & NE corner all w/pedimented projecting gables; oriel on west side; ; pedimented entrance on porch; oval stained glass window; rectilinear tripartite attic windows	B	Y	N	INT	Y	N	Large WF, WC carriage house w/hip SSMroof; broken eave dormers; sliding doors & windows intact; modillions/decor. match house	
Decor. shingles in gable ends; verge boards w/carved ends; brackets over bay window on 2nd floor; 1 orig. chimney intact NOTE: enclosed exterior stair to 2nd floor dates to mid- to late- 20th century; metal edge on roof; 1 chimney added	B	Y	N	INT	Y	N	Small barn; WF; wood novelty siding; sliding doors & attic window intact	
Probably a pattern book house; principle façade oriented to east side yard; 6-over-1 sash windows; blinds; simple elegant proportions; straight balustrades & sq. columns on porches; pedimented canopy on small entry porch; dormers w/pedimented gables & windows w/multi-paned transoms	B	Y	N	INT	Y	N	WF; WC small barn w/hay door & sliding doors intact; contemporary w/house	
Wrap-around front porch has spindled frieze, pediment over entry, turned columns & scroll sawn balustrade; door & window surrounds w/dentils; entrance door has sidelights; battered banding between 2nd floor & attic; window blinds; 2nd story balcony on west has scroll sawn brackets & pendant beneath; 2nd floor porch on east has frieze & balustrades to match 1st floor porch below; tripartite attic windows w/multi-paned colored glass;	B	Y	N	INT	Y	N	1-1/2 story barn w/cross gable roof; WF; WC & WS; transom over entry door; hay door & windows intact; o.h. door installed	bluestone walkway
Wrap-around front porch has turned ballustrades, scroll sawn skirting, decorative brackets & braces; multi-paned attice window; NOTE: Other decorative elements appear to have been removed or covered over when house was sided w/vinyl	B	Y	N	INT	Y	N	Hay door & sliding barn doors intact	
False gambrel roof w/pentice on first floor & side of 2nd story; orig. 1-story sunroom off east side; shingles on gable end	N							
Corner pilasters; porch columns; pedimented front porch w/skirting; NOTE: decorative details removed or covered over	G	Y	N	INT	Y	N	WF; WN + B&B; intact except for o.h. door	stone walkway
Square porch columns (Craftsman details); classic 4 Sq. form except side porch	SH							
Columns on porch; partially glazed; pedimented porch entrance; window surrounds; stained glass transom on first floor front window; 1-story rear addition dates to mid-20th century	B	E	N	INT	Y	N	WF; WC; hay door intacts; slightly altered	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-1-7	146	ELM ST	B	SFR	DOM	SD	CR	c1905	2	CP	RE-1	N	WF	WC	N	CL	H	S	N	OR	INT	INT	F	INT	INT	Y	N
55.20-1-12	School Prop'ty	ELM ST																									
68.5-2-11	147	ELM ST	B	MFR	DOM	MD	A4	c1915	2	SQ	N	H	WF	WC	VS	CB	H	A	N	OR	REP	R	F	ENC	ALT	Y	N
68.5-2-10	149	ELM ST	B	MFR	DOM	MD	A4	c1915	2	SQ	N	N	WF	WC	N	CB	H	A	N	OR	REP	INT	F	INT	INT	Y	N
68.5-2-9	151	ELM ST	B	MFR	DOM	MD	A4	c1915	2	SQ	N	H	WF	WC	N	CB	H	A	N	OR	REP	R	F	REP	INT	Y	N
68.5-2-8	153	ELM ST	B	MFR	DOM	MD	A4	c1915	2	SQ	N	N	WF	WC	VS	CB	H	A	N	OR	REP	R	F	REP	INT	Y	N
68.5-2-7	155	ELM ST	B	SFR	DOM	SD	A4	c1915	2	SQ	N	H	WF	WC	N	CB	H	A	N	OR	REP	INT	F	ENC	INT	Y	N
56.17-1-8	156	ELM ST	B	SFR	DOM	SD	QA	c1890	2	O	N	NH	WF	WC	N	CL	H	A	N	N	INT	INT	F	REM	ALT	Y	N
68.5-2-6	159	ELM ST	B	SFR	DOM	SD	GO	c1885	2	UPW	RE-1	N	WF	WC & BB	N	CL	CG	SSM	N	N	MIX	INT	F	ALT	INT	Y	N
56.17-1-9	160	ELM ST	B	SFR	DOM	SD	QA	c1885	2	O	N	H	WF	WC	N	CL	H	A	Y	N	INT	INT	FWS	REP	INT	Y	N
68.5-2-5	161	ELM ST	B	MFR	DOM	SD	GO	c1885	2	O	N	H	WF	WC	N	CL	CG	A	Y	N	REP	INT	FWS	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Front projecting bay w/pediment; pedimented dormers w/decorative shingles; rectilinear tri-part attic window; multi-paned stained glass transoms; porch is partially glazed, has Doric columns, scroll sawn skirting, modillions; beaded joints on foundation stonework	G	Y	N	INT	Y	N	WF; WC; 1-story/1-stall garage c1920	
SEE 155 WASHINGTON AVE								
1 of 4 identical 4 Squares (see 149, 151, 153 Elm Street); mid-20th century rear 1-story addition	SH						Late 20th century	
1 of 4 identical 4 Squares (see 147, 151, 153 Elm St.); attic window still intact w/multi-paned colored glass; porch is partially glazed	SH							
1 of 4 identical 4 Squares (see 147, 149, 153 Elm St.); attic window still intact w/multi-paned colored glass	N							
1 of 4 identical 4 Squares (see 147, 149, 151 Elm St.)	N							
Very similar to 4 houses to east except blt. as a SFR (see 147, 149, 151 & 153 Elm St.); Doric column on porch which is now 1/2 enclosed; attic window intact w/multi-pane colored glass NOTE: rear 1-story shed roof addition dates to mid-20th century	G	N	N	INT	Y	N	WF; WN & BB; 1-story 1-stall garage attached to house w/shed/breezeway; c1930	
Front & side 2-story bay windows w/winged and bracketed gable ends; half-circle attic windows w/multi-paned colored glass; transom windows w/diamond panes NOTE: 3-stall 1-story rear addition dates to late 20th century	N							
Turned porch columns; exposed & carved rafters; door & window surrounds; board & batten gable ends & under eave; NOTE: porch railing has been replaced/altered; decorative elements have been removed; foundation has been repaired with concrete block; slat blinds are a later addition	G	N	N	ALT	Y	Y	WF; asphalt siding w/brick pattern; dates to c1920; contributing due to date/form NOTE: endangered due to lack of maintenance	
Carved exposed rafter ends; 2-story rear addition dates to early 20th century; unique roof-lines with projecting gable ends; 1st floor front bay window with box projection over; NOTE: limestone foundation has been painted	G	N	N	INT	Y	Y	1-story; 1-stall; WF; WN; dates to c1920; NOTE: doors falling off	
Porch has unique "turned" square columns (replacements for orig.?), scroll sawn railing & braces; window & door surrounds	G	N	N	INT	N	N	2-stall WF w WC dating to late 20th century	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-1-10	162	ELM ST	B	SFR	DOM	SD	QA	c1885	2	O	RE	NH	WF	WC & WS	N	CL	H	S	Y	N	INT	INT	F	REM / ENC	INT	Y	N
68.5-2-4	163	ELM ST	B	SFR	DOM	SD	A4	c1915	2	SQ	N	N	WF	WC	MS	CB	H	A	N	OR	MIX	INT	F	REP	INT	Y	N
56.17-1-11	164	ELM ST	B	SFR	DOM	SD	QA	c1905	2	O	RE-1	N	WF	WC	N	CB	H	A	N	N	INT	INT	F	INT	INT	Y	N
68.5-2-3	165	ELM ST	B	SFR	DOM	SD	QA	c1905	2	O	N	N	WF	WC	N	CL	FG	S	Y	OR	INT	INT	S	ALT / REM	ALT	Y	N
56.17-1-12	166	ELM ST	B	MFR	DOM	MD	CC	c1920	2	O	RE-2	H	WF	WC	STU	COB	CG	A	N	N	INT	INT	F	REP	ALT	Y	N
68.5-2-2	167	ELM ST	B	SFR	DOM	SD	CC	c1920	2	O	SE-2	N	WF	WC	N	PC	FG	A	N	N	MIX	INT	F	INT	INT	Y	N
68.5-2-1	171	ELM ST	B	C	DOM	SD	BUN	c1930	1	O	SE	N	WF	WC	N	RFC	G	A	N	OR	INT	REP	FF	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES Description
	Type	Match	dgevs	Integ	Contrib	Endan		
2-story bay window on east side; octagonal 3rd-floor tower w/slate roof & fishscale shingle siding betw. 2nd fl. & attic; shingle siding on 2nd fl.; paneled banding & decorative slanted boards in gable ends; transom & side lights on paneled front door; multi-paned diamond pattern colored glass in attic windows; NOTES: broken pedimenton front door surround is probably a later modification; original wrap-around porch has been drastically altered w/front portion removed & side portion enclosed (has concrete foundation)	G	N	N	INT	N	N	WF; WC; mid- to late-20th century	
NOTE: any decorative detailing has been removed or covered over with metal siding	B	N	N	INT	Y	N	WF; WC; c1915; Jerkin head on front gable; hay door intact; o.h. doors installed	
Entrance door surround w/dentils; transom on front windows 1st & 2nd floors; modillions on front projecting pendimented gable over bay; shingled gable ends; porch has pediment over entrance, battered & shingled railing, Doric columns, partially glazed; fan light in attic window & diamond panes in uppermost attic window	G	Y	N	INT	Y	N	WF; WC 1-story, single stall garage w/hip roof that has battered walls to match those on front porch of house; c1920	
Decorative shingling on gable ends; turned columns on side porch; exposed carved rafters; brackets w/pendants on 2nd story of 2-story bay window on east side; NOTE: front portion of original wrap-around porch removed leaving side portion	B	Y	N	INT	Y	N	WF;WS & WN; 2-story w/Jerkin head front gable; hay & sliding doors intact; c1905	
Window & door surrounds; cobblestone foundation (venerer?); exposed rafters; carved ends on verge boards; transom on front windows; 1-story rear lean-to may be original; NOTE: appears that windows on 2nd fl. center were removed; parking lot to west is on this lot & associated w/funeral home across the street	B	Y	N	INT	Y	N	WF; WC; 2nd floor windows intact; o.h. doors installed	
Jerkin head cross gables; shingled gable ends w/battens; square paneled columns on porch; brackets & expose rafters	B	Y	N	INT	Y	N	WF; WC; Jerkin head front gable; hay door & cupola intact; o.h. door installed	
Classic Bungalow roof w/large dormer; square-paneled columns; single car attached garage on east side; NOTE: o.h. door has replaced original garage door; canopied entrance added to front porch for funeral functions	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-1-13	172	ELM ST	B	SFR	DOM	SD	QA	c1885	2	O	N	N	WF	WC WS & BB	N	CL	CG	A	N	N	INT	INT	FF & S	INT	INT	Y	N
68.5-2-54	108	HARDER AVE	B	MFR	DOM	MD	RR	c1990	1-1/2	RR	N	N	WF	VS	N	PC	G	A	N	N	INT	INT	FE	INT	na	N	N
56.18-7-1.1	114	LARK ST	B	EDU	EDU	SCH	COL-GOTH	1913	2-1/2	CP	SE & RE	NH	M	B	N	PC	FL	U	N	N	REP	REP	na	na	INT	Y	N
56.18-4-21	117	LARK ST	B	MFR	DOM	SD	IT	c1885	2	O	RE-2	N	WF	WC	VS	CL	FL	U	N	N	INT	ALT	FF & S	REP	INT	Y	N
56.18-4-20	119	LARK ST	B	SFR	DOM	SD	IT	c1885	2	O	RE & SE	N	WF	WC	VS	CL	FL	U	N	N	REP	REP	FWS	ALT / REP	ALT	Y	N
56.18-4-19	121	LARK ST	B	MFR	DOM	SD	IT	c1885	2	O	SE-2	NH	WF	WC	N	CL	FL	U	N	N	INT	INT	FWS & S	REM / REP	INT	Y	N
56.18-4-18	123	LARK ST	B	MFR	DOM	MD	IT	c1885	2	O	SE-2	N	WF	WC	VS	CL	FL	U	N	N	INT	INT	FWS & S	REP	INT	Y	N
56.18-7-2	124	LARK ST	B	MFR	DOM	SD	GO	c1880	2	O	RE-1-1/2	H & NH	WF	WC & BB	N	CL	CG	A	Y	N	INT	INT	FF & S & S	INT	INT	Y	N
56.18-4-17	125	LARK ST	B	SFR	DOM	SD	IT	c1885	2	O	RE-1	NH	WF	WC	N	CL	H	SSM	N	N	INT	INT	FF	REP	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Hipped top to cross-gable roof; decorative shingling on gable ends; decor. verge board; decor. brackets at bays & gable ends; board & batten banding betw. 2nd fl. & attic; 1-story bay windo w/bd. & batten banding; oval stained glass window on front; multi-paned colored glass attic window; colored glass transom in 1st floor of 2-story bay on east side; beaded joints on foundation; HISTORICAL NOTE: Rose St. was the driveway to this house prior to the construction of Elm St.	B	Y	N	INT	Y	Y	WF; WC & BB; 2-story addition on east side (historic); rear lean-to; NOTE: endangered due to being open to elements & animal intrusion (missing window panes)	
Rehabilitation Support Services (RSS) house; modern bldg on what appears to be a previously undeveloped parcel; 1927 Sanborn shows deep narrow lot along Harder Ave. w/an accessory bldg for 409 West Main St. which has since been demolished	N							
Originally Cobleskill High School, Wm. T. Townes, Architect; now "Aker School/Head Start"; crenolated parapet; limestone window surrounds; limestone projecting entrance pavilion; raised basement; interior has marble steps w/tile inlay NOTE: school has been adapted to new uses & to meet code requiremets (rear h.c. entrance)	N							
Intact cornice; pediments on roof & porch over entrance; projecting pavillion; door & window surrounds; blinds on west façade windows	B	N	N	INT	Y	N	Intact wagon door, hay door & attic window; standing seam metal roof; c1885	
Form is all that remains as evidence of original Italianate style as all decorative details have been removed or covered over in remodeling	B	N	N	INT	Y	N	WF; WC resided w/Vinyl to match house; c1885; hay door remains; o.h. door installed	
Wide cornice; orig. double front doors; door & window surrounds; 2-story side ell; NOTE: 1-story side addition may be remains of wrap-around front/side porch that has been enclosed; chimney added	B	Y	N	ALT	Y	N	WF; WC ; o.h. doors & window installed	
Built as 2-family dwelling; wide cornice; window & door surrounds; window blinds; 2 added chimneys; NOTE: front portion resided w/vinyl, rear portion remains WC	B	Y	N	ALT	Y	N	WF; WN; o.h. doors & window installed	
Board & batten siding at attic level; cross gable roof has Jerkin head on front; porches all have scroll sawn braces & railings; transom windows over doors; multi-paned attic windows; lattic DGEVS	G	N	N	na	Y	N	WF; WC mid-20th century attached to rear addition to house	
Cornice; window surrounds; small brackets on porch cornice; NOTE: porch has been repaired-battered walls & Craftsman type columns uses; chimney added	B	N	N	INT	Y	N	WF; WN; c early 20th century	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.18-7-3	126	LARK ST	B	SFR	DOM	SD	U	c1890	2	O	RE	NH	WF	WC	VS	CL	FG	SSM	N	N	REP	INT	FE	ALT	ALT	Y	N
56.18-4-16	127	LARK ST	B	HEA	DOM	SD	RA	c1945	1	O	N	N	WF	B & WC	N	CB	G	A	N	N	MIX	INT	N	na	ALT	N	N
56.18-7-4	128	LARK ST	B	SFR	DOM	SD	GO	c1885	2	UPW	RE	N	WF	WC & BB	N	CL	CG	A	N	N	INT	INT	FF	INT	INT	Y	N
56.18-7-5	130	LARK ST	B	SFR	DOM	SD	CR	c1910	2	O	RE & SE	NH	WF	WC	VS	TC	CG	SSM	N	N	INT	INT	FF & R	INT & ALT	INT	Y	N
56.18-4-15	131	LARK ST	B	SFR	DOM	SD	IT	c1880	2	O	RE-2 & SE-2	H	WF	WC	VS	CL & CB	H & G	A	N	N	INT	REP	S	INT	INT	Y	N
56.18-7-6	132	LARK ST	B	SFR	DOM	SD	QA	c1905	2	O	N	N	WF	WC	VS	CL	H	A	N	N	INT	REP	FF	INT	INT	Y	N
68.6-5-2	209	MACARTHUR AVE	SI	IND	IND	MFG	na																			N	N
68.6-5-4	214	MACARTHUR AVE	B	SOC/ HAL	C/T	OFF	U	c1920	1	O	N	N	WF	WC	VS	U	G	A	N	N	REP	REP	N	na	ALT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Bldg has been remodeled; full front & side porches have been removed; newer canopy front entrance porch added; east side sunroom addition c mid-20th century; all decorative details have been removed or covered over	G	N	N	na	N	N	WF; WC garage c mid 20th century replaced a 2-story barn shown on 1904 Sanborn; now connected to house w/breezeway	
Appears to have been converted from domestic/single dwelling for doctor's office w/changes to windows & doors	N							
Board & batten on upper 1/2 of 2nd fl.; fluted wood banding; turned columns on front porch; window & door surrounds; 1904 Sanborn indicates that orig. porch was in front right corner only & was expanded to a full front porch after this date NOTE: siding has holes from insulation work	B	N	N	INT	Y	N	Small WF; WC barn w/hay loft door intact; o. h. door installed; c1900	bluestone sidewalk in front ; bluestone walkway to house
Door & window surrounds; multi-paned colored glass attic window w/arched & garlanded trim over; Doric columns on front porch; NOTE: 2nd fl. added to rear ell late 20th century	B	Y	N	ALT	Y	N	WF; WC; orig sliding doors intact; window added to 2nd fl.	
Double bracketed cornice; 2-story bay window on Lark St. façade w/orig. windows; false windows w/blinds; early rear addition w/porch; scroll sawn brackets on porch; metal roof on side bay; NOTE: may be missing a front porch facing North St.; chimney added	B	Y	Y	INT	Y	N	WF; WN; front gable standing seam metal roof; rubblestone foundation; hay door intact; o.h. door installed	
Front bay window; 1-story bay on east side; NOTE: decorative elements may have been removed or covered over during residing ; chimney added to west side	G	Y	N	INT	Y	N	WF;COM; gable roof; c early 20th century	low "Lock-crete" retaining wall; terraced rear yard w/lock-crete retaining wall (all late 20th century improvements)
Unimproved/vacant lot (portion of parcel east of Mill Creek) w/remains of former bldg. pad; 1883 Birdseye shows property as vacant; 1892 Sanborn labels as "S. Courter Planing Mill" & 1904 repeats this w/"Sash, Door Blind & Table Factory" added; 1927 Sanborn labels as the "Harder Silo Co., Inc. mfg of farm silos" NOTE: Building(s) west of creek on this property are not included in the historic district	N							
Very simple bldg w/out decoration, formerly an office for a lumber yard (1904 & 1927 Sanborns) w/1/2 of the footprint enclosed, the other 1/2 an open porch; appears to have been moved slightly; American Legionnaires report that Sam Aldrich's plumbing business occupied this bldg for some years	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.6-6-10	226	MACARTHUR AVE	B	SFR	DOM	SD	MH	c1960	1	O	SE	NH	Metal	MS & COM	U	CB	FG	SSM	N	N	INT	INT	S	INT	INT	N	Y
68.6-6-15	230	MACARTHUR AVE	B	C	IND	IS	U	c1970	1	O	N	N	M	CB	N	CB	FG	A	N	N	INT	INT	N	na	INT	N	N
68.6-6-14	232	MACARTHUR AVE	B	C	IND	IS	U	c1970	1	O	N	N	M	CB	N	CB & MS	FG	A	N	N	INT	INT	N	na	INT	N	N
68.6-6-13	234	MACARTHUR AVE	B	MFR	DOM	MD	MH	c1980	1	O	N	NH	WF	T111	N	CB	FG	A	N	N	INT	INT	S	INT	INT	N	N
68.6-6-12	238	MACARTHUR AVE	B	MFR	DOM	SD	IT	c1885	2	O	N	NH	WF	WC	VS	CL	FL	SSM	N	N	MIX	INT	F & S	F ALT S INT	ALT	Y	N
56.17-8-33	545	MAIN ST	B	C	C/T	FIN	IT	1864	3	O	RE-1	H	M	B	N	CL	FL	U	na	na	INT	REP	na	na	INT	Y	N
56.17-8-32	547	MAIN ST	B	C	C/T	SPE	IT	1864	3	O			M	B	PA	CL	FL	U	na	na	MIX	REP	na	na	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Mobil home w/corrugated metal siding & side addition; bldg date is outside the period of significance for this district; Sanborn maps show that most bldgs on lots along old Perrine St. were cleared to move the street southward to line up with MacArthur St. (formerly Courter Lane & Belanger)	N							
Concrete window lintels; 1 single stall garage door on east side at rear of bldg.; Sanborn maps show that most bldgs on lots along old Perrine St. were cleared to move the street southward to line up with MacArthur St. (formerly Courter Lane & Belanger)	N							
Later bldg; single stall garage entrance on front facade & 1 on west side at rear of bldg; similar to bldg @230 MacArthur St.; outside junk storage; Sanborn maps show that most bldgs on lots along old Perrine St. were cleared to move the street southward to line up with MacArthur St. (formerly Courter Lane & Belanger)	N							
No decorative features; Sanborn maps show that most bldgs on lots along old Perrine St. were cleared to move the street southward to line up with MacArthur St. (formerly Courter Lane & Belanger)	N							
Double bracketed cornice; fluted columns w/octagonal capitals on east side porch (railing missing); new entrance w/gable canopy created on front facade (north side) c1980; appears on 1883 Birdseye; 1887 Sanborn doesn't include property; on 1892 Sanborn map	G	N	N	ALT	N	N	1-stall WF garage w/hip roof; T-1-11 siding; SSM roof; o.h. garage door, newer access door	
"West Brick Block/Bank Block" [Frake] Early bank bldg. - labeled as such on 1866 map & 1887, 1892, 1904 & 1927 Sanborns; 1 of a series of 3 bldgs, later 6 nearly identical bldgs (see also 547, 549, 551, 553 & 555 Main St); dentiled cornice w/end brackets; limestone headers missing over arcaded 2nd fl. windows on front facade; arched windows on 3rd fl.; corner lot determined trapazoidal footprint; 1-story rear loading dock c late 1800s; decor. storefront w/pilasters, modillions & transoms over doors	N							
"West Brick Block/Bank Block" [Frake]; 1 of a series of 3, later 6 nearly identical bldgs (see also 545, 549, 551, 553 & 555 Main St); dentiled cornice w/end brackets; limestone lintels & headers; on 1866 map & 1883 Birdseye; Sanborns: 1887 "Mill'y", 1892 "Hardw.", 1904 "Gro.", 1927 store; NOTE: appears to have been sandblasted	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.6-1-6	548	MAIN ST	B	C & MFR	C/T	SPE	CR	1898	3	O			M	B	N	CL	FL	U	na	na	MIX	MIX	na	na	INT	Y	N
56.17-8-31	549	MAIN ST	B	C	C/T	SPE	IT	1864	3	O			M	B	N	CL	FL	U	na	na	INT	REP	na	na	INT	Y	N
56.17-8-30	551	MAIN ST	B	C	C/T	SPE	IT	c1865	3	O			M	B	N	CL	FL	U	na	na	INT	INT	na	na	INT	Y	N
68.6-1-7	552	MAIN ST	B	C	DOM	SD	GR	1840	2	O	SE-1		WF	WC	N	CL	FG	SSM	N	N	REP	REP	N	na	INT	Y	N
56.17-8-29	553	MAIN ST	B	C	C/T	SPE	IT	c1865	3	O			M	B	PA	CL	FL	U	na	na	INT	ALT	na	na	ALT	Y	Y

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Mann Block; limestone headers & lintels; Romanesque arch on 3rd floor of center projecting pavilion; garland & swags on pressed sheet metal cornice; 1904 Sanborn labels as "Jeweler, D.G., Plumber" NOTE: fire in Dec. 1945 seriously damaged bldg, including "Index" newspaper office then housed there; parapet wall has been rebuilt w/blonde brick; right storefront intact, left storefront altered	N							
"West Brick Block/Bank Block" [Frake]; 1 of a series of 3, later 6 nearly identical bldgs (see also 545, 547, 551, 553 & 555 Main St); dentiled cornice w/end brackets; limestone lintels & headers on 2nd & 3rd fl. windows; on 1866 map & 1883 Birdseye; Sanborns: 1887, 1892 & 1904 "Dry Goods", 1927 store	N							
1 of a series of 6 nearly identical bldgs (see also 545, 547, 549, 553 & 555 Main St); dentiled cornice w/end brackets; limestone lintels & headers on 2nd & 3rd fl. windows; on 1866 map & 1883 Birdseye; Sanborns: 1887 "Hardw.", 1892 "Hats & Dry Goods", 1904 & 1927 "Bank"; storefront w/transom intact except w/replacement windows; frieze at top of 1st floor bracketed w/modillions	N							
Front bay window on 2nd fl.; pedimented front gable w/decor. panels; corner pilasters; paneled doors, blinds; storefront windows added to front of dwelling; Ionic columns flanking door in 1-story side ell; 1866 map labels as "Jerome Kromer"; Moved eastward on lot to make room for development of the Mann Block at corner of Main & So. Grand; 1887 Sanborn shows in orig. location at corner & labels as "Dwelling"; 1892 Sanborn: in orig. location, "Jewelry" in 1-story portion, "Dwelling" in 2-story part; 1904 Sanborn: now in present location, labeled "Office & Gro."	B	Y	N	INT	Y	N	WF; WC w/front gable in rear of bldg.	
1 of a series of 6 nearly identical bldgs (see also 545, 547, 549, 553 & 555 Main St); 2-story concrete block bldg immediately behind, may have been rear addition c1930; appears on 1866 map & 1883 Birdseye; Sanborns: 1887 "Hardw. & D.G.", 1892 & 1904 "Hardw.", 1927 "Hardw. & Paints"; NOTE: endangered due to being a burned out shell w/out a roof (bldg behind is also roofless shell); parapet w/dentiled cornice has been removed; 1st fl. storefront has been altered w/wood infill; remnants of cornice evident; bldg. painted	G	N	N	INT	N	N	1-story concrete block bldg w/shed or flat roof c1970	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.6-1-8	554	MAIN ST	B	C	C/T	SPE	IT	c1900	2	O			WF	WC	B & COM	CL	FL or S	U	N	N	REP	ALT	na	na	ALT	Y	N
56.17-8-28	555	MAIN ST	B	C	C/T	SPE	IT	c1865	3	O	N	H	M	B	PA	CL	FL	U	na	na	INT	ALT	na	na	INT	Y	N
68.6-1-9	558	MAIN ST	B	C	C/T	SPE	MOD	c1950	1-1/2	O	N	N	M	CB	N	CB	FL	A	N	N	INT	INT	na	na		N	N
68.6-1-11	560	MAIN ST	B	C	C/T	SPE	U	c1860	2	O			WF	WC	W	CL	G	SSM	N	N	ALT	ALT	N	na	ALT	Y	N
68.6-1-10.1	PKG	MAIN ST	ST	PKG	C/T	SPE	N																			N	
56.17-8-27	561	MAIN ST	B	C	DOM	HOT	IT	1875	3	O	RE-3 (2)	NH	M	B	N	CL	G	U	N	N	INT	INT	F	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Orig. architectural character has been covered up or removed; not on 1887 or 1892 Sanborns; 1904 Sanborn shows 2-story WF bldg labeled "Clo."; same footprint/bldg on 1927 Sanborn NOTE: storefront altered, pentice betw. 1st & 2nd fls. dates to mid-20th century	N							
1 of a series of 6 nearly identical bldgs (see also 545, 547, 549, 551 & 553 Main St); dentiled cornice w/ 4 brackets; limestone lintels & headers on 2nd & 3rd fl. windows; on 1866 map (location of Post Office) & 1883 Birdseye; Sanborns: 1887, 1892, 1904 & 1927 "Drugs"; corner tower canopy over entrance to enclosed exterior wood stairway to upper floors; NOTE: storefront altered w/wood & stone veneer infill construction, bow windows	N							
Mid-20th century bldg on the site that had a "Meat & Gro. store" on it in 1892; metal entrance canopy; aluminum façade on upper portion of front façade w/random stone veneer below	N							
False front later addition on an early residence; possibly on 1866 map ("J.H.Ferguson"? ); on 1883 Birdseye; 1887 & 1892 Sanborns: "P.O."; 1904 Sanborn, "Saloon"; NOTE: original cornice & other decor. details removed or covered over by mid- to late- 20th century alterations	N							
Parking lot now associated w/bldg to west; site of earlier 3 3-story bldgs: "Gro., Meat & Confy/Photo. 3rd fl." (1904 Sanborn); 3 2- & 3-story bldgs on 1927 Sanborn	N							
"Hotel Augustan" C-plan w/flanking front pavilions w/half circle attic windows; recessed center bay & front porch; heavy, bracketed cornice; 2-story veranda w/2nd story balconies w/brackets; scroll sawn braces on front porch; front windows on west projecting pavilion are intact w/Corinthian pilasters; ornate cast iron window & door lintels & headers; on 1883 Birdseye, 1887 Sanborn (rear ell dining room removed sometime after 1927), also shows large horse & wagon sheds associated w/hotel behind & east of hotel, since demolished; <u>History of Schoharie County 1875-1882</u> states this was site of the "Brick House" which was operated as an inn & burned down in 1873; 1-story rear addition c1960; also 3-story rear elevator addition	N							Planters added on sidewalk level, both sides of stone entrance stairway

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-8-26	567	MAIN ST	B	C	C/T	SPE	IT	c1875	3	O		H	M	B	N	CL	FL	U	na	na	INT	INT	N	na	INT	Y	N
56.17-8-25 56.17-8-24	569 - 571	MAIN ST	B	C	C/T	SPE	IT	1873	3	O			M	B	PA-1/2	CL	FL	U	N	N	INT	REP	N	na	INT	Y	N
56.17-8-23	573	MAIN ST	B	C	C/T	SPE	CR	c1930	4	O	N	N	M	B	N	U	FL	U	N	N	INT	INT	N	na	INT	Y	N
68.6-2-11	574	MAIN ST	B	C	C/T	SPE	IT	c1890	2	O	N	H	M	B	N	CL	FL	U	N	N	MIX	INT	N	na	INT	Y	N
56.17-8-22	575	MAIN ST	B	C	C/T	SPE	MOD	1873	2	O	N	N	M	B	N	CL	FL	U	N	N	INT	INT	N	na	INT	N	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Decorative elements match those on adjacent "Commercial Building" to east; stairway on side connects 2nd fl. of both bldgs; fleur de lis & acanthus leaf decor. on cornice w/brackets & rope turning at base; cast iron window headers & lintels; intact storefront window except transoms infilled; scroll sawn brackets; orig. double doors intact; on 1883 Birdseye; 1887, 1892 & 1904 Sanborns label as "Drugs"; 1927 Sanborn "Drugs & Paints"	N							
Highly ornate double bracketed & dentiled cornice w/ name & date of bldg on parapet (Commercial Building 1873); fleur de lis & acanthus leaf carvings on bracketscast iron window headers & lintels; on 1883 Birdseye; Sanborns: 1887 "Jewelry & B&S Hats", 1892 "Jewelry & Boys S.", 1904 "Jewelry & Clo.", 1927 "S. & Ins. Off."; NOTE: storefront windows & doors have been altered, except for door w/transom to central stairway [property divided for tax purposes]	N							
Slender, trapizodal infill bldg on site of earlier 2-story wood frame structure; blt after 1927 (per Sanborn map) but before Opera House was remodeled as indicated by 4-story wall along east side; simple classical details on upper floors w/dentiled cornice, brick detail at corner; first floor storefront done in Art Modern style w/"Vitrolite" glass cladding; earlier bldgs house clothing shop (1887), millinary (1892) & cigar shop (1904)	N							
Cast iron storefront w/columns & 2nd fl. window headers w/dentils; paneled & double bracketed cornice w/modillions; limestone headers & lintels on west side windows; exposed limestone foundation on west façade; early small 1-story rear entrance addition 1892 & 1904 Sanborn maps: "Gro., Office; Printing, Press in Basement" NOTE: storefront windows replaced & transoms removed	N							
West end of remnant of the former 1873 Jacob Russell Block aka Opera House Block, & Lower Brick Block, patched windows evident on front & back; on 1883 Birdseye; 1887 & 1892, 1904 & 1927 Sanborns indicate there were orig. 3 floors w/stores on 1st floor; brick piers on front façade; 3rd floor removed & front facade modernized c1930 (street level storefront is historic w/Art Moderne Vitrolite glass) & c1950 (upper stories, brick veneer & altered windows)	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																												
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan	
68.6-2-6	576	MAIN ST	B	C	C/T	SPE	IT	c1900	2	O	N	NH	WF	WN	B & W	CL	FL	U	N	N	ALT	ALT	N	na	ALT	Y	N	
56.17-8-21 56.17-8-20	577 - 579	MAIN ST	B	C	C/T	SPE	MOD	c1880	2	O	N	N	M	STU	N	C	FL	U	N	N	INT	REP	N	na	INT	N	N	
68.6-2-7	578	MAIN ST	B	C	C/T	SPE	ROM	1898	2	O	N	N	M	B	N	CL	FL	U	N	N	MIX	ALT	N	na	INT	Y	N	
68.6-2-8	584	MAIN ST	B	C	C/T	DEP	ROM	c1870	3	O	N	NH	M	B	N	CL	FL	U	N	N	INT	ALT	N	na	INT	Y	N	
68.6-2-9	PKG	MAIN ST	ST	PKG	DOM	HOT	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	N	na
56.18-7-20	589	MAIN ST	B	C	DOM	HOT	GR	c1828 1842 & 1882	2	O	RE (2)	H	WF	WC	N	CL	G	SSM	N	N	MIX	REP	FF	INT	INT	Y	N	

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Highly decorated cornice w/large & small brackets, dentils & pediment; not on 1887 or 1892 Sanborn maps; 1904 Sanborn: "Gen'l Store & Photo-2nd fl" NOTE: front façade altered in late 20th century w/brick & wide wood clapboard, shutters, shingled pentice	N							
Eastern 3/4ths of remnant of former 3-story Opera House Block [see 575 Main St., above]; has 3 storefronts on 2 tax parcels; on 1883 Birdseye; 1887 Sandborn labels 1st fl. stores as "Glassware & C", "Dry Goods" and "Gro." NOTE: 3rd story removed & modernized w/altered 2nd floor windows & street level storefronts c1950	N							
Corbeled & arcaded brick band on 2nd fl. beneath pressed metal cornice w/panels & dentils; raised center parapet w/bldg date; 1904 Sanborn: "Printing, Repos. Eng." & "P.O."; 1927 Sanborn: "Hardware, Paints & Oils" NOTE: orig. storefront altered, transoms infilled	N							
Early bldg: "New Regulator Store"; Borst & Ryder Dry Goods 1871; B.H. Lambert Block 1898; raised center parapet w/modillions; brick corbeling; arcaded 2nd & 3rd fl. windows; soldier course brick work on 2nd & 3rd fl. front façade; decorative limestone medallions at spring line of arcaded windows; large early department store; on 1883 Birdseye; 1887 Sanborn: 3-story brick bldg labeled "Dry Goods, Clothing & C., YMCA 3rd Fl."; 1892 Sanborn: "D.G., B&S"; 1904 Sanborn: "Ryder & Hodge Brothers" w/"Lodge Hall"; 1927 Sanborn: "Lambert, Snyder & Warner Dept. Store" & "P.O."; appears to have been adapted for Woolworth's c1930; NOTE: bldg has been sandblasted; numerous rear basement level additions in brick & concrete	N							
Partially paved parking lot for 584 Main St. above; site of demolished American Hotel (on 1887-1927 Sanborn maps)	N							
Gable roof, full front porch w/decor. braces, & clapboard siding are historic features remain; This was the "United States Hotel"; Roscoe's <a href="#">History of Schoharie County 1875-1882</a> indicates the bldg. was constructed at early date, bought by Abr. Lawyer in 1842 who changed it from a store to a hotel by an addition made around that date; Levi Kilts purchased it in 1868 and made an extensive addition in c1882	N						SEE # 5 Union Street (may be the Ice House for the hotel, renovated for office/residential use)	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.18-7-19	593	MAIN ST	B	MFR	DOM	MD	CR	c1875	2	O	REP	H & NH	WF	WC	N	CL	FG	SSM	N	N	REP	INT	FF & S	INT	INT	Y	N
68.6-3-3	596	MAIN ST	B	C & MFR	DOM	SD	GR	c1850	2	CP	RE-2	H	WF	WC	MS (on part)	CL	G	SSM	N	N	INT	INT	FF	INT	INT	Y	N
56.18-7-18	597	MAIN ST	B	C & MFR	DOM	SD	GR	1850	2	O	RE-2	H	WF	WC	N	CL	FG & H	SSM	N	N	INT	INT	FE	ALT	INT	Y	N
68.6-3-4	600	MAIN ST	B	C & MFR	DOM	SD	QA	c1895	2	O	N	H	WF	WC	COM	CL	HIP	A	Y	N	MIX	REP	FWS & R	INT & REP	ALT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Corner pilasters/boards; 2-story porch added by 1927 per Sanborn Map (none prior); bldg appears on 1883 Birdseye; 1887, 1892 & 1904 Sanborns list as "Bakery" (show oven); 1927 Sanborn lists as "Dwelling"	N							
Pediments 1st fl. porch entrance & gable ends; 2-story corner pilasters @ front & rear; sidelights & transom in front door surround; symmetrical end wall chimneys; turned ballustrades & spindled frieze on porch; appears on 1883 Birdseye & possibly as C. Holmes' residence on 1866 map & later Sanborns	B	Y	N	INT	Y	N	WF; WC c1850 barn w/hay door & attic window intact; garage doors installed in 1st 1/2 of 20th century	
Massive cornice & architrave; corner pilasters; window & door surrounds; NOTE: this building could be earlier than the 1850 date on the plaque (front gable portion of bldg. appears orig.) 1866 maps notes "M. Watson" in this location (Martin Watson, son-in-law of Abr. Lawyer, ran the U.S. Hotel 1842-1852) Sandborn maps show that the porch ran along the front gable end plus portion of side ell in 1887, 1892 & 1904 & along entire bldg. front by 1927; NOTES: Porch altered to current front entrance configuration after 1927; foundation parged w/concrete & patched w/concrete block; solar panels on roof; chimney added	B	Y	N	INT	Y	Y	Carriage House & poss. caretaker residence; WF; WN 2-story w/chicken coop added off west side; loosed well back from house; c1850; endangered due to lack of maintenance	
Octagonal tower w/witch's hat conical roof & weather vane (1st floor portion removed by 1927); decor. verge board; cut corner/front pay w/decor. brackets; pedimented porch roof w/sunburst infill repeated in DGEVS on front & side gables; multi-paned colored glass attic window; NOTE: bldg may have had decor. wood shingle siding, now covered by composition siding; a simple front gable "storefront" addition on west side of house after 1927 per Sanborn map to house commercial use; addition cut off side of porch & extends to front lot line, has 1st fl. pentice; 2-stall garage addition off rear of commercial gable section & 1-story basement addition off rear of main bldg. dating to later 20th century	B	Y	N	ALT	Y	Y	WF; composition siding; vertical wood plank garage doors; form still evident; hay door intact	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.18-7-17	603	MAIN ST	B	MFR	DOM	SD	CR	c1860	2	CP	SE-2	H	WF	WC	N	CL	CG	A	N	N	INT	INT	FE	INT	INT	Y	N
68.6-3-5	604	MAIN ST	B	C	DOM	SD	CR	c1890	2	UPW	RE	H	WF	WC	COM	CL	CG	S	N	OR	REP	REP	FWS	INT	INT	Y	
56.18-7-16	609	MAIN ST	B	SFR	REL	CHR	QA	1893	2	O	N	N	WF	WC, WS & BB	VS	CL	H	A	Y	N	REP	INT	FWS & R	INT & ALT	INT	Y	N
68.6-3-6	610	MAIN ST	B	CIVIC	GOV	FIR	CLR	2001	1	O	SE	N	M	VS & B	N	CB	G	A	N	N	INT	INT	N	na	INT	N	N
56.18-7-16	615	MAIN ST	B	REL	REL	CH	GO	1868	na	na	RE	H & NH	M	B	N	CL	G	A	N	na	INT	REP	na	na	INT	Y	N
68.6-3-7	616	MAIN ST	B	SFR	DOM	MD	CLR	c1910	2	CP	RE-1	N	M	B	N	CL	G	S	N	OR	INT	INT	FF	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Bay windows flank octag. front entrance porch; 2nd front porch along east ell; door & window surrounds; Palladian window on 2nd floor over front entrance; corner pilasters; graduated clapp. siding; scroll sawn brackets; scroll sawn skirting on side front porch; 1866 map may indicate that "Mrs. Lawyer" lived here; comparison of 1887, 1892 & 1904 Sanborn maps show that the house was moved to the west (1-1/2 story rear ell was removed then) to make room for new Lutheran parsonage blt. next to church in 1893	B	Y	N	INT	Y	N	Large 2-story w/1-story rear ell (may be orig. barn) & small lean-to shed off rear.; WF; WC & WN; 2 hay doors; SSM roof; o.h. doors installed	
Front door surround w/leaded glass sidelights & transom; fluted Corinthian columns on front porch; 2-story corner pilasters; blt betw. 1887 & 1892 per Sanborn maps; wrap-around porch added betw. 1904 & 1927 (Sanborns); 1-story rear ell added after 1904	N							
Parsonage for Lutheran Church to east; projecting gables over 2-story bays (front & side) w/carved brackets; 3-story octag. corner tower w/fish scale shingles; bd & batten banding betw. 2nd story & attic; decor. rectang. battens on gable ends; orig. entrance door w/side lights; porch has turned columns, fluted braces w/scroll sawn inserts, dentils, scroll sawn railing panels & skirting; NOTE: vinyl siding on 1st 2 stories only; wood trim on attic level above	N							
Cobleskill Fire Station set back from Main Street w/monument sign at street frontage; 5-bay station house; cupola w/weather vane; decor. shingling; pentice; side ell has false fronts on south & west sides w/brackets & dentils; raised brick kneewall	N							
Broach spire on steeple w/lancets; spires at front corners of bldg.; engaged piers; stained glass windows w/lancets; rear school addition is illustrated on 1904 Sanborn (not before); has stepped parapet on front; flat roof (or very slight pitch); HC entrance/elevator late 20th century addition	N							
Georgian style Colonial Revival; 2 front bay windows flanking front door; limestone header over front door; limestone lintels on windows; Venetian window in center dormer; dormers have pilasters; cornice w/modillions; engaged chimneys on end walls w/limestone caps; red colored mortar used w/the red brick; decor. shingles on gable ends; 1/2 fanlight windows/w/ decor. headers; doesn't show up until 1927 Sanborn	B	Y	N	INT	Y	N	Carriage House c1880; WF; WC; fanlight in gable dormer; hay door intact	Terraced rear yard & retaining wall on east side of lot

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.6-3-8	620	MAIN ST	B	SFR	DOM	SD	GR	c1850	2	SP	RE-2 RE-1	H	WF	WC	COM	LIM - C	G	SSM	N	H	INT	INT	FF	REP	INT	Y	N
56.18-7-15	623	MAIN ST	B	MFR	DOM	MD	SE	c1880	2	O	RE	H	WF	WC	N	CL	M	WS	N	OR	INT	INT	FF	INT	INT	Y	N
56.18-7-14	627	MAIN ST	B	MFR	DOM	SD	CR	c1865	2	UPW	RE	H	WF	WC	N	CL	CG & F	SSM	N	N	MIX	INT	FF	INT	INT	Y	N
68.6-3-9	628	MAIN ST	B	MFR	DOM	SD	CR	c1870	2	UPW	SE-2 & RE-1	H	WF	WC	N	CL	CG	SSM	N	N	INT	REP	FE	REP	INT	Y	N
56.18-7-14	631	MAIN ST	B	MFR	DOM	SS	U	c1870	2	O	N	H	WF	WN	N	CL	FG	A	N	N	ALT	ALT	N	na	INT	Y	N
56.18-7-14	633	MAIN ST	B	SFR	DOM	SD	IT	c1870	2	O	RE	H	WF	WC	N	CL	FL	U	N	N	INT	INT	FF	INT	INT	Y	N
68.6-3-10	634	MAIN ST	B	SFR	DOM	SD	CR	c1870	2	UPW	SE-1	H	WF	WC	N	CL	FG	A	N	N	INT	INT	FP	REP	INT	Y	N
56.18-7-13	637	MAIN ST	B	SFR	DOM	SD	BUN	c1915	1	SQ	N	N	WF	WC & WS	N	CL	G	A	N	OR	INT	INT	FF	INT	INT	Y	N
68.6-3-11	638	MAIN ST	B	SFR	DOM	SD	CR	c1870	2	UPW	SE-2	H	WF	WC	MS	CL	FG	A & SSM	N	N	INT	REP	FE	REP	ALT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Scroll sawn decor. brackets on front & side porches; pedimented front dormer (may be a historical addition); pedimented end gables; bay on east side; appears on 1866 map & later Birdseye/maps; roof addition and rear ells probably historic additions; foundation appears to be limestone rubble under concrete parging; NOTE: cornice is now covered by metal siding; 1-stall rear garage addition dates to mid-20th century	N							
Mansard roof w/gabled dormers & octagonal shingles (slate or wood shingles?); false windows w/blinds; double bracketed cornice w/scroll sawn wood decor.; highly ornamented window headers on 2nd fl.; orig. porch railing; oriel window @SW corner added; portion removed from rear by 1904; on 1883 Birdseye & 1892 Sanborn	B	Y	N	INT	Y	N	Front Gable; WF; WC; hay door & sliding doors intact	
Dentiled cornice & window headers; Doric columns, capped newel posts on front porch; front door surround is paneled, has pilasters; orig. slate roof below present SSM roof	B	Y	N	INT	Y	N	Very large barn; WF; WC; c1865; o.h. doors installed on east side; reported to be part of Kennedy Farm	2 mature deciduous trees in front yard flanking entrance walk
Window & door surrounds; 1-story wing shows up on 1883 Birdseye; 2nd story on wing added by 1904 & converted to duplex by 1927 (per Sanborn maps)	N							
Later barn associate w/"Kennedy Farm" blt. after 1904; hay door removed; o.h. doors installed; exterior enclosed stair to 2nd fl. added (after 1927)	N							
Double bracketed cornice w/wide overhanging eaves; projecting pavilion; large window headers; paneled entranceway w/orig. double doors; porch sides are glazed; NOTE: brick insert in east foundation wall (for missing chimney?); rear 2-story addition off rear ell has limestone found.	B	Y	N	INT	Y	N	Orig. barn from Kennedy Farm (also a blacksmith shop per occupant); WF; WC; 1927 Sanborn labels bldg as a "Dairy"; sign on it: "1802"	Limestone step at curb line has "Kennedy" carved in it
Simple & elegant proportions; attic window; false window on east façade w/blind; appears on 1883 Birdseye; arched window & door openings on porch NOTE: poor pointing on foundation; porch repair probably dates to c1915	B	Y	N	INT	Y	N	WF; WC; broken eave dormer; o.h. door installed	retaining wall between side yard & rear yard
Classic Bungalow style intact; balcony on front gable dormer; scroll sawn porch balustrades/railings, partially enclosed; lattice porch skirting; 6-over-1 sash windows; exposed rafters under eaves	G	Y	N	INT	Y	N	WF; WC; small lean-to addition	
Pedimented front entry porch; bldg appears on 1883 Birdseye; NOTE: virtually all orig. architectural decor. has been lost or covered over	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.18-7-12	641	MAIN ST	B	SFR	DOM	SD	GR	c1840	2	SP	SE-2 (2)	N	WF	WC	N	CL	CG	A	N	N	MIX	INT	F 2 & S	INT	INT	Y	N
68.6-3-12	642	MAIN ST	B	MFR	DOM	SD	CR	c1870	2	O	N	N	WF	WC	N	CL-SD	FG	SSM	N	N	INT	ALT	N	na	ALT	Y	Y
56.18-7-11	645	MAIN ST	B	SFR	DOM	SD	CR	c1910	2	CP	RE-2	N	WF	WC	N	CL	H	S	N	OR	INT	INT	S	INT	INT	Y	N
56.18-8-21	653	MAIN ST	B	MFR	DOM	SD	CLR	c1880	2	SP	RE-1-1/2	H & NH	WF	WC	N	CL	H	A	N	OR	MIX	REP	FF & S & S	INT & ALT	INT	Y	N
56.18-8-20	659	MAIN ST	B	MFR	DOM	SD	IT	c1850	2	CP	RE	NH	WF	WC	N	CL	CG	A	N	N	MIX	INT	FE	INT	INT	Y	N
56.18-8-19	665	MAIN ST	B	MFR	DOM	SD	QA	c1850	2	O	FE	H & NH	WF	WC	VS	CL	CG	SSM	N	N	MIX	REP	F - 2	REP	ALT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
High style/early Greek Revival w/2-story corner pilasters; projecting pavilion w/pedimented front gable w/dentils; front door surround & window headers w/Greek Fret; side lights & transom on front door; dentiled cornices; low railing on front porch; 1-story bay window & 2-story bay window on east facade with hexagonal side porch between; 1st fl. windows appear to be intact w/only some 2nd fl. windows replaced; Appears to have been the Lutheran Parsonage indicated on 1866 map	N							Curved stone walkway up to front entrance; mature spruce tree
Attic window; window surrounds; appeared on 1883 Birdseye; NOTE: architectural detail stripped or covered over	N							
Corner lot w/main entrance facing North Street but full side porch on south elevation makes it appear to front on Main; Roman porch columns; projecting entrance pavilion w/dentiled pediment over shallow front entrance porch; dormer w/dentiled pediment and fanlight over entranceway; short upper sash w/vertical muntins; stained glass transom on first fl. front windows; transom & sidelights on front entrance; door; 14-over-14 sash window on 2nd floor of east facade; bldg. appears on 1883 Birdseye view	N							Later brick walls beside front entrance steps
Venetian window in front gable; arched attic windows in side gable dormer; false window blind; center chimney appears to be orig.; bldg. appears on 1883 Birdseye view; NOTES: chimney added on east side; one-story rear ell extending eastward dates to mid- to late-20th century;	N							
Probably an early bldg that was updated w/Italianate features c1880; swag decor. on front gable pediment; window & door surrounds; bay windows w/panels underneath flank octagonal front entrance porch; octagonal capitals on porch columns; scroll sawn brackets on porch; 2-story corner pilasters; attic window has scroll sawn header	B	Y	N	ALT	Y	Y	2-story WF; WC c1880; very altered with new windows & doors, but retains overall form	
Appears to be an early house (upright & wing plan) remodeled in late 19th century in the Queen Anne style (possibly creating multiple dwellings at that time); appears on 1883 Birdseye; 1-story lead-to on rear looks orig.; NOTE: has been resided & remodeled with virtually all windows & doors replaced or repaired, decor. features covered over or removed	B	Y	N	INT	Y	N	Large WF, WC c 1880 barn; hay door & attic window intact; o.h. doors installed	Bluestone walkway to front doors

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.18-7-21	PKG	MAIN ST	ST	PKG	DOM	SS	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	N	na
68.5-3-16	105	MILL CREEK LA	B	SFR	DOM	SD	RA	c1940	1	O	SE-1	NH	WF	COM	N	CB	G	A	N	N	INT	INT	F	REP	INT	Y	N
68.5-3-27	-	MILL CREEK LA	B	C	C/T	SPE	na	c1880	2	na	SE-2	N	WF	WC	N	CL	FG	A	N	N	INT	ALT	na	na	INT	Y	N
68.5-3-27 & 68.5-3-29	-	MILL CREEK LA	ST	BRI	TRA	ROAD	CC	c1940	na	na	na	na	WF & Metal	na	na	CL	na	na	na	na	na	na	na	na	INT	Y	N
68.5-3-29 68-5-3-21	114	MILL CREEK LA	B	SFR	DOM	SD	CR	c1895	2	CP	N	N	WF	U	WS & T1-11	CL	G	A	N	N	INT	INT	N	na	ALT	Y	N
68.5-3-29	116	MILL CREEK LA	B	SFR	DOM	SD	CR	c1905	2	CP	N	N	WF	WC	N	CL	G	SSM	N	N	INT	REP	F	INT	INT	Y	N
68.5-3-22	235	NORTH GRAND ST	B	C	C/T	SPE	RDS	c1970	1	O	na	na	WF	U	VS	C	FL	U	na	na	na	na	N	na	na	N	N
56.17-8-34	236	NORTH GRAND ST	B	MFR	DOM	SD	CR	c1910	2	O	RE-2	N	WF	WC	N	CL - C	H	S	N	OR	INT	INT	FE & S	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Village Parking Lot; historically the site had barns & other bldgs. associated w/the United States Hotel; on 1883 Birdseye; 1887 Sanborn: 1 brick bldg & "Hotel Barn, & Wood Ho."; 1892 Sanborn: "Gro., Hotel Stables, Horse Shed, Stables and Feed Yard, & Wood Ho."; 1904 Sanborn: "Printing Office, Horse Shed, Farmer's Feed Yard, Shed & Shed"; 1927 Sanborn: Auto Rep., Oil Stge., Garage - Capacity 20 cars, Auto Rep., Shed"	N							
Windows have 32 panes; scroll sawn patio railing; screened-in porch; NOTE: front ell probably added later	N							
Vertical plank banding on front façade; NOTE: This barn was once a commercial bldg. with the label "stge. & auto ho." on 1927 Sanborn map; front of original bldg was cut off to provide access road to houses to west	N							
Plain rectilinear bridge over Mill Creek with wood deck, Craftsman-like railings & posts; metal lanterns on end posts	N							
Bldg. present on 1887 & 1892 Sanborns, not on 1883 Birdseye; addition on south side c1940; resided with wood shingles & T1-11 NOTE: separate tax parcel is enclosed & rear yard for this dwelling	N							
Porch w/decorative brackets, turned columns; simple elegant proportions; NOTE: On same parcel as 114 Mill Creek Lane	G	Y	N	INT	Y	N	Small 1-story, 1-stall garage WF, WN siding c1920	
1927 Sanborn map indicates property was site of "Gasol. Stat'n"; however, that bldg has been replaced w/present Mobil Station w/canopy; property vacant on earlier Sanborn maps	N							
Dentiled cornice & pediments; modillions; 2-story bay window w/projecting pedimented gable on south; Roman columns on porches; window & door surrounds; fanlight attic windows; was the site of a "store" on 1866 map; house shown on 1883 Birdseye & 1887, 1892 & 1904 Sanborns was demolished & replaced with present structure some time after 1904	B	Y	N	INT	Y	N	WF: WC barn w/front gable slate roof; hay door & windows intact; o.h. door installed & pentice over it added to front	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-8-35	240	NORTH GRAND ST	B	SFR	DOM	SD	IT	1850	2	SP	RE	H	WF	WC	N	CL	FL	SSM	N	N	INT	INT	FF & S	INT	INT	Y	N
68.5-3-20	241	NORTH GRAND ST	B	MFR	DOM	SD	IT	c1870	2	SP	RE-1-1/2	NH	WF	WC & BB	N	CL	FL	SSM	N	N	INT	INT	FF & S & S	INT	INT	Y	N
56.17-8-36	242	NORTH GRAND ST	B	MFR	DOM	MD	CC	c1930	2	O	N	N	WF	WC	N	CL	FG	A	N	N	INT	INT	FF & S	INT	INT	Y	N
56.17-8-37	244	NORTH GRAND ST	B	MFR	DOM	SD	GR	c1850	2	UPW	RE-1	H	WF	WC	N	CL	CG	SSM	N	N	INT	INT	F	INT	INT	Y	N
68.5-3-19	245	NORTH GRAND ST	B	C	IND	CMM	MOD	c1960	2	SQ	RE	N	M	B	N	PC	FL	U	N	N	INT	INT	N	na	INT	N	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Early bldg w/plaque indicating 1850 constr. date; evidently remodeled to Italianate style in later 19th century; front porch elements--scroll sawn brackets & braces--do not match Doric columns on side porches; wide cornice; window & door surrounds; leaded glass transom over front door & side lights; blinds; cut limestone front steps; 1-story bay on north side dates to early 20th century; possibly "W. Shafer" on 1866 map; on 1883 Birdseye, 1887, 1892, 1904 & 1927 Sanborns	B	N	N	ALT	Y	N	WF; WC; later than house c1900, o.h. door installed & 1st fl. door widened, windows installed	
Double bracketed cornice w/wide overhanging eave, attic windows in frieze, wood slat panels & banding; parapet wall; scroll sawn railing; on 1883 Birdseye; on 1887 Sanborn w/barn; 1892, 1904 & 1927 Sanborns all show side porch & bay window on so. side added; enclosed exterior stairway dates to mid-20th century	B	Y	N	INT	Y	Y	WF; WC, 2-story barn w/hay door, sliding doors intact; c1870; endangered due to structural problems & lack of maintenance	Bluestone front & side walkways
False gambrel w/false shed-roof dormers; gambrel pentice on 2nd fl. front façade tied into 1st fl. pentice which wraps around house; wood shingles on 1st fl. pentice; 2nd story balcony over front porch; grouped front windows; side entrance	G	Y	N	INT	Y	N	WF; WN garage; o.h. door installed	
Wide cornice; pedimented front gable; Greek fret window headers; corner pilasters; Corinthian columns on porch; may be the G. Rockafellow" home labeled on 1866 map; on 1883 Birdseye; front porch altered over the years: 1892 Sanborn shows side portion of front porch fronting the wing set back; 1904 Sanborn shows that portion removed & small front entrance porch; 1927 Sanborn shows present configuration: NOTE: 1 front window converted to door	G	N	N	INT	N	N	4-stall late 20th century WF structure	
Plain modern telephone exchange bldg that replaced the dwelling that had been converted for office use for Otsego & Delaware Telephone Co. per 1927 Sanborn	WHS	N	N	INT	Y	N	1-story WF, WC garage/warehouse w/hip roof; pressed metal siding on north & south sides; located along rear property line; siding & older window surrounds; blt. betw. 1904 & 1927 per Sanborn maps; o.h. door added	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-8-38	250 & 252	NORTH GRAND ST	B	MFR	DOM	SD	IT	c1860	2	SP	RE-2	N	WF	WC	N	CL	FL	A	N	N	INT	INT	FF & S	INT	INT & ALT	Y	N
68.5-3-18	251& 253	NORTH GRAND ST	B	MFR	DOM	SD	GR	c1850	2	SP	RE-2	H	WF	WC	N	CL	FG	A & SSM	N	N	INT	INT	FF	INT	INT	Y	N
56.17-8-39	254	NORTH GRAND ST	B	SFR	DOM	SD	GR	c1850	2	O	RE & SE	N	WF	WC	N	CL	CG	S	N	N	REP	REP	F	INT	INT	Y	N
68.5-3-17	255	NORTH GRAND ST	B	SFR	COM	SD	A4	c1915	2	SQ	N	N	WF	WC	N	CL	H	A	N	OR	INT	INT	FE & S	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
<p>MAIN BLDG (252 North Grand): 2-story bay windows, north &amp; south facades; door &amp; window surrounds; porch has scroll sawn railing &amp; frieze panels, turned columns; multiple decor. elements on double bracketed cornice - rope scallop &amp; reverse ogee designs; cresting on roof; possibly "J.W. Lawyer" on 1866 map; 1883 Birdseye illustrates gable roof; appears on 1887 &amp; 1892 &amp; later Sanborns; BACK BLDG (250 North Grand): Orig. a barn for &amp; probably dates to same period c1860; has been adapted for use as a duplex; front porch appears to have been removed from the back of the house &amp; appended to new entrance on west side of this bldg.; resided &amp; probably placed on a new foundation (concrete bl.); 2-story barn shows up on 1887 Sanborn &amp; 1883 Birdseye</p>	G	N	N	INT	N	N	4-stall garage on rear of property serving both 250 and 252 North Grand St.	
<p>Fluted Doric columns on front porch; curved bottom of front gable pediment; leaded stained &amp; colored glass on 1 side window; on 1887, 1892 &amp; 1904 Sanborns; side bay w/cross gable roof &amp; 1-story ell on north side added by 1927; barn labeled "stge" on 1927 Sanborn NOTE: details lost or covered over w/vinyl siding</p>	B	Y	N	ALT	Y	N	WF, gambrel roof 2-story c1850 barn has been converted to residence (251 North Grand St.); vinyl clapb. matches house	
<p>Major alterations c1900 to transform a early Greek Revival into a more imposing, Classical revival structure; 2-story pavilion added w/curved 2nd story balcony underneath; corner pilasters; massive cornice w/pedimented projecting front gable &amp; side gable; fanlights for attic windows in gable ends; flagstone front porch floor; possibly the A.C. Smith house shown on 1866 map; appears on 1883 Birdseye w/orig. configuration; 1887 &amp; 1892 Sanborns show rear wing and porch on south 1/2 of front; 1904 Sanborn shows full front porch not as deep as present one &amp; rear ell removed; 1927 Sanborn does not yet show present front porch configuration but has the full width rear wing in place</p>	B	Y	N	INT	Y	N	WF; BB; c1850; rear 1-story section	2 mature deciduous trees flank driveway
<p>Barrel vaulted roof on front porch, w/arch above entry, square columns; front door w/transom &amp; side lights; window surrounds; stair window north side; Craftsman details; west side of larger side porch is glazed; not on 1904 Sanborn; on 1927 Sanborn together w/1-story garage</p>	G	Y	N	INT	Y	N	WF, WC, 2-stall c1915 garage Hip roof, slate shingles	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-8-40	258	NORTH GRAND ST	B	SFR	DOM	SD	CR	c1910	2	O	RE-2	N	WF	WC	N	CL	H	A	N	OR	INT	INT	FE	INT	INT	Y	N
56.17-8-1	260	NORTH GRAND ST	B	MFR	DOM	SD	IT	c1870	2	SP	RE-2	N	WF	WC	COM	CL	H	A	N	N	INT	INT	FF	INT	INT	Y	N
68.5-3-15	263	NORTH GRAND ST	B	SFR	DOM	SD	SE	c1860	2	CP	RE-2	N	WF	WC	N	CL	CGAM	S & SSM	N	OR	INT	INT	S S & R	INT	INT	Y	N
56.17-7-16	264	NORTH GRAND ST	B	SFR	REL	CHR	QA	c1880	2	O	RE-1	N	WF	WC	N	CL	FG	A	Y	OR	INT	TIN	FF	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Front door surround w/sidelights, leaded glass transom & dentiled cornice; Corinthian columns & pilasters on front porch; box oriel on north façade w/stained glass window & brackets; bracketed eaves; corner pilasters; 2-story bay window w/projecting gable on south side; attic windows: large fanlight & Venetian under gable w/small pilasters; not on 1883 Birdseye; 1892 & 1904 Sanborns show bldg w/different footprint & diff. siting on property (evidently demolished); 1927 Sanborn indicates present config. & barn too	B	Y	N	INT	Y	N	WF; WC barn c1910 w/hay door & windows intact; o.h. doors installed	
Tall (down to floor) windows on front façade; scroll sawn brackets, skirting & frieze on front porch; double bracketed cornice w/pendants; blinds on front 2nd story windows; front door w/transom; doesn't show clearly on 1883 Birdseye; "Frame dwelling & barns" noted on 1887 Sanborn; current footprint illustrated on 1892 Sanborn	B	Y	N	INT	Y	N	WF; WC carriage house c1870; broken eave dormer w/gable; panel below attic window; NOTE: 1 window added	
Broken pediment over front door; decor. slate slabs/shingles on mansard roof; corner & front pilasters; bracketed cornice; gambrel ends on rear bay of rear ell; decor. column capitals on rear/side porch; door & window surrounds; possibly H.Smith's residence on 1866 map; on 1883 Birdseye; on 1887 Sanborn w/full front porch & labeled: "2 + Fr. Rf." 1904 Sanborn labels as 3-story, still shows full front porch + large "Private" barn immediately east of Mill Creek; 1927 Sanborn still has lg. barn	N							
Parsonage for Methodist Church; Double & triple columns on front porch; 2 full floor to ceiling windows on front; window surrounds w/garland swags surrounds on attic window, multi-paned w/colored glass; transom over front entrance door; round window on north side of rear ell; Methodist Church in this location noted on 1866 map; 1883 Birdseye shows church w/residence behind; 1887 Sanborn notes "frame church, frame dwellings, frame barns"; 1892 illustrates both church & present bldg.w/house in present configuration w/2nd front porch on north side stepped back; 1904 Sanborn shows this porch extended further out from front of bldg to create a full front porch as in present configuration: NOTE: barns & other accessory bldgs have been removed to provide room for classroom addition to church east of the house	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-14	265	NORTH GRAND ST	B	SFR	DOM	SD	A4	c1915	2	SQ	N	N	WF & M	WS & B	N	CL-C	H	A	N	OR	INT	INT	FE & S	INT	INT	Y	N
56.17-7-17	266	NORTH GRAND ST	B	SFR	DOM	SD	CA	c1970	1	CP	RE-1	N	M	B	N	CB	G	A	N	OR	INT	INT	N	na	INT	N	N
68.5-3-13	267	NORTH GRAND ST	B	SFR	DOM	SD	GO	1840	1	O	RE	N	WF	BB	N	CL	G	SSM	N	OR	INT	INT	FE	INT	INT	Y	N
68.5-3-12	269	NORTH GRAND ST	B	SFR	DOM	SD	QA	c1885	2	O	RE-1 & SE	H	WF	WC & WS	N	CL	CG	A	N	OR	INT	INT	F	INT	INT	Y	N
56.17-7-18	270	NORTH GRAND ST	B	MFR	DOM	SD	IT	c1870	2	SP	RE-2 SE-2	H	WF	WC	N	CL-C	FL	U	N	N	INT	INT	FF	INT	INT	Y	N
56.17-7-19	272	NORTH GRAND ST	B	SFR	DOM	SD	CR	c1930	2	SP	RE-1	N	WF	WC	N	RFC	FG	A	N	N	INT	INT	FE	INT	INT	Y	N
56.17-7-20	274	NORTH GRAND ST	B	SFR	DOM	SD	QA	c1900	2	O	SE-1	H	WF	WC & WS	N	CL	H	A	N	OR	INT	REP	FE	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Colonial Revival architectural treatment of Am. 4-Sq.; massive beige brick chimneys; 1st fl. is beige brick w/limestone lintels & headers; 2nd floor clad w/wood shingles, wood window surrounds; diamond and varied muntin patterns in windows; pedimented dormer w/tripartite attic window; porches have triple Roman columns at corners, stone piers, dentiled cornices; large porch on south side; bracketed cornice & eaves; not on 1883 Birdseye or 1904 Sanborn; 1927 Sanborn illustrates both house & garage	G	Y	N	ALT	Y	N	WF; WS 1-story garage w/hip roof & pedimented dormer; chimney; a 2-stall garage added off the front	White picket fence & arbor around south side yard
House w/square footprint illustrated on 1927 Sanborn demolished; bow window, sidelight	N							"Lockcrete" retaining wall along So. side of property
Board & batten cladding; steeply pitched gable roof & canopies over windows; projecting center pavilion w/broken eave dormer over front entry, window has Tudor arch; decor. verge-board; carved brackets & braces on front porch; heavy turned posts & columns; exposed false purlin ends [brackets]; on 1883 Birdseye; on 1904 Sanborn w/orig. barn since demolished [1887 & 1892 Sanborns do not include the property]; 1927 Sanborn shows orig. barn removed, replaced by neighboring house to south	G	Y	N	INT	Y	N	Small WF; WC 1-story garage c1930 (does not appear on 1927 Sanborn) matches architecture of house w/board & batten siding; front gable roof	
Decor. shingles on gable ends; hipped roof dormer; window & door surrounds; intact porch w/ lattice skirting & square columns; side ell added before 1927 per Sanborn [earlier Sanborns do not include this property]	G	N	N	INT	Y	N	Small WF; WC 1-story flat roofed garage c1930 (does not appear on 1927 Sanborn)	
Highly decor. door & window surrounds w/brackets; small central pediment on front of roof; scroll sawn braces & skirting on porch; horizontal attic windows; 1-story bay window on south side; 2-over-2 sash windows; appears on 1883 Birdseye, on 1904 & 1927 Sanborns w/out 2-story rear ell off south side of house	G	N	N	-	N	-	C1970 2-stall garage w/vinyl siding	
Simple proportions; fanlight attic window in front gable; fanlight transom & sidelights around entrance door; square columns; 6-over-1 windows; infill bldg. bit. after 1927	B	N	N	INT	Y	N	WF; WN 2-story barn blt c 1900; o.h.doors installed; barn is located mostly behind 270 No. Grand but painted to match 272	
Window & door surrounds; Venetian attic window w/curved & lozenge-shaped panes; rounded front porch added betw. 1904 & 1927; 1-story sunroom addition off south side blt after 1927; does not seem to appear on 1883 Birdseye	G	Y	N	INT	Y	N	WF; WC; 1-story garage w/hip roof & dormer; probably blt later than house, c1920	Fountain in front yard, arbor, lattice fence

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-11	275	NORTH GRAND ST	B	SFR	DOM	SD	GO	c1840	1-1/2	O	RE-2	H & NH	WF	BB	N	CL	G	SSM	N	OR	REP	INT	FE	INT	INT	Y	N
68.5-3-68	277	NORTH GRAND ST	B	SFR	DOM	SD	CR	c1900	2	O	N	H	WF	WC	N	CL-C & P	FG	SSM	Y	OR	INT	INT	FF	INT	INT	Y	N
56.17-7-21	278	NORTH GRAND ST	B	MFR	DOM	SD	IT	c1870	2	SP	RE-2	NH	WF	WC	COM	CL	H	A	N	N	INT	ALT	N	REM	ALT	Y	Y
68.5-3-10	279	NORTH GRAND ST	B	MFR	DOM	SD	QA	c1895	2	O	N	H	WF	WC	N	CL	H	A	N	N	INT	INT	F	INT	INT	Y	N
56.17-7-22	280	NORTH GRAND ST	B	SFR	DOM	SD	IT	c1870	2	O	SE-2 & RE-1	N	WF	WC	N	CL	H	SSM & A	N	N	INT	INT	F	INT	INT	Y	N
56.17-7-1	282	NORTH GRAND ST	B	SFR	DOM	SD	CR	c1890	2	O	SE-1	NH	WF	WC	VS	CL	CG	SSM	N	N	MIX	REP	F	ENC	ALT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Board & batten cladding; steeply pitched gable roof; shed canopies over windows; broken eave dormers on front facade; massive 1-story side ell w/hipped roof; front bay window; bracket on front porch; on 1904 & 1927 Sanborns w/small 1-stall garage or shed illustrated: rear porch, deck, shed, 2nd fl. rear ell additions after this date	N							
Wide cornice board; broken eave dormer on south side; rear 1-story lean-to an early addition; porch screened in (early); door & window surrounds; on 1904 & 1927 Sanborns	N							
Double bracketed cornice & eaves w/pendants & dentils; window surrounds; on 1883 Birdseye; [1887 & 1892 Sanborns do not extend this far up Grand]; house only partially shown on 1904 Sanborn but a full front porch evident; 1927 Sanborn shows ff porch & barn; endangered property due to lack of maintenance & vacancy	B	Y	N	INT	Y	Y	WF; WC; 2-story barn w/front gable roof; c1870; hay door intact; o.h. doors installed	
Arched front porch (may be an early alteration); intact orig. double doors at front entry; banding between 1st & 2nd fl.s; 1-story box bay on south; board & batten frieze on cornice; garage or carriage house addition w/false front off south side of house by 1904; not on 1883 Birdseye	N							
Door & window surrounds; wide overhanging bracketed eaves & wide cornice w/panels & horizontal attic windows in frieze; 1-story bay window on south side w/pilasters & panels; front porch has scroll sawn railing, braces w/spindled frieze; side porch is more Italianate in decoration indicating front porch may have been altered later on, perhaps when south portion was enclosed; on 1883 Birdseye [1887, 1892 & 1904 Sanborns do not extend this far up Grand] on 1927 Sanborn	B	Y	N	ALT	Y	N	WF; WC; now vinyl sided, o.h.doors; 2nd fl. windows appear orig.	
Late 19th century house that has been substantially altered: garage addition off north side & octagonal front porch/vestibule random ashlar stone piers w/beaded joints added after 1927, oversized fanlights in attic windows of both house & garage, what was probably a full front porch has been enclosed; orig. decor. details either removed or covered with vinyl siding; appears that garage addition may have been an original porte cochere converted; [property not shown on 1887, 1892 or 1904 Sanborn maps]	N							Octagonal front steps match added front porch

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-4-7	PARK	NORTH GRAND ST @ HIGH ST	B SI ST	REC	IND	MFG	U	c1900	1	O	RE	NH	M & WF	STO & WC	N	CL	G & S	SSM	N	N	INT	INT	N	na	INT	Y	N
56.17-6-9	287	NORTH GRAND ST	B	MFR	DOM	SD	CR	c1930	2	O	N	NH	WF	WC & B	MS	CL-C & S	CG	A	N	N	INT	INT	F	ENC	INT	Y	N
56.17-6-8	289	NORTH GRAND ST	B	SFR	-	-	SPL	c1970	1	SPL	N	N	WF	MS & B	N	PC	CG	A	N	N	INT	INT	F	INT	INT	N	N
56.17-6-7	291	NORTH GRAND ST	B	SFR	DOM	SD	QA	c1890	2	O	RE-2	N	WF	WC	N	CL	CG	A	N	N	INT	INT	FF & R	ENC	INT	Y	N
56.17-6-6	295	NORTH GRAND ST	B	MFR	DOM	SD	IT	c1870	2	O	RE-2	H & NH	WF	WC	N	CL	H	SSM	N	N	INT	INT	FF	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Originally the site of the former Harder Silo Co. sold to A.L. Norton in 1914; frame bldgs razed at that time; one-story stone bldgs were the boiler and engine house; the park was envisioned by Margaret G. Golding (wife of Judge Wm. H. Golding) who donated the frame bldg addition; property was sold to Village of Cobleskill in 1950 & the adjoining tract donated by NYS College to make a total of 25 acres; devel. of picnic area in 1951; funds from the 1952 Bicentennial Celebration were dedicated to the project; sign erected in 1968; photo shows stone dam on the property; 2 pavilions (1 large, 1 small) btl. in recent years along with a wooden bridge over the creek constructed by SUNY Cobleskill AG Eng. Club; basketball court behind WF wing of main bldg.; 1-story sq. brick pump house w/hip roof lies west of creek; cut limestone bldgs w/limestone lintels & headers over windows & doors	G	N	N	INT	Y	N	Single-stall WF garage w/hip roof, orig. doors, wood shingle & novelty siding; c1930	2 large granite blocks on east end of bridge; basketball court behind rear wing
Unique house btl. after 1927 per Sanborn; pediments on gable ends, pentice between 1st & 2nd fl.s; lozenge shaped muntins in windows & diamond shaped attic window; brick piers w/inlaid stonework on what was probably originally an open porch (now glazed & infilled); brick work on lower portion of 1st fl.;	G	Y	N	INT	Y	N	WF; WC garage w/gable room (SSM roof);c1930; o.h. doors installed otherwise intact	
Split Level Modern	N							
Decor. gable ends w/shingles & curved & straight battens; attic windows w/multi-paned colored glass; dentils on cornice; projecting front gable at attic level; 2-story bay on south façade w/gable roof brackets; decorative skirting on porch; unclear as to whether on 1883 Birdseye; on 1927 Sanborn [earlier Sanborns do not include this property]; NOTE: front & rear porches have been enclosed w/glazing	B	Y	N	INT	Y	N	WF; WC; carriage house perhaps w/caretaker's residence above; c1890; some alterations w/2nd fl. remodeled as apt (newer door) ; o.h. doors installed	
Wide bracketed cornice; door & window surrounds; porch railing w/croll sawn decor. inserts, braces & pediments, frieze; porch columns; floor plan appears to have been added to over time w false front over side porch; on 1883 Birdseye; 1904 & earlier Sanborns do not include property]; 1927 Sanborns indicates it is a SFR	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.17-5-4	299	NORTH GRAND ST	B	SFR	DOM	SD	CR	c1880	2	CP	RE-2 & SE-1	NH	WF	WC	N	CL	G	A	N	OR	MIX	INT	FE & R	INT	INT	Y	N
56.18-7-10	105	NORTH ST	B	SFR	DOM	SD	CC	c1925	2	SQ	FE-1	N	WF	STU	N	PC	H	A	N	N	INT	INT	N	na	INT	Y	N
56.18-7-22	-	NORTH ST	SI	VAC			na																				
56.18-8-22	106	NORTH ST	B	SFR	DOM	SS	U	c1870	2	O	SE - 2 SE - 1	H & NH	WF	WC	VS	CL & C	CG	A	N	OR	REP	REP	N	na	ALT	Y	N
56.18-7-9	107	NORTH ST	B	MFR	DOM	MD	CR	c1910	2	O	N	N	WF	WC	N	PC	H	A	N	OR	MIX	INT	FF	INT	INT	Y	N
56.18-8-23	108	NORTH ST	B	SFR	DOM	SD	IT	c1870	2	SP	SE - 2	H	WF	WC	N	CL - C	FL	U	N	N	INT	INT	S	ALT	INT	Y	N
56.18-7-8	109	NORTH ST	B	SFR	DOM	SD	IT	c1870	2	SP	RE & SE-1	N	WF	WC	COM	CL	FL	U	N	N	INT	INT	FF	REM	INT	Y	N
56.18-8-24	110	NORTH ST	B	MFR	DOM	SD	IT	c1870	2	SP	RE-2 & SE-1	H	WF	WC	COM or VS	CL	H	SSM	N	N	INT	INT	FE	ALT	ALT	Y	N
56.18-7-7	111	NORTH ST	B	SFR	DOM	SD	DC	c1930	2	SQ	RE-1 & SE-1	N	WF	WC	VS	RFC	G	A	N	N	REP	REP	S	INT	INT	Y	N
56.18-8-25	112	NORTH ST	B	SFR	DOM	SD	IT	c1870	2	UPW	SE-2 & RE-1	N	WF	WC	N	CL-C	H	SSM	N	N	INT	INT	F	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Georgian style Colonial Revival but no end chimneys; corner pilasters; dentiled cornice; entrance door surround w/fanlight transom & sidelights; window surround w/Doric columns above; shutters on 1st fl. windows, blinds on 2nd fl.; fanlight on gable end; blonde brick w/limestone details on rear chimney; 1-story sunroom off south side - windows intact; small 1-story rear addition dates to mid-20th century; on 1883 Birdseye [early Sanborn maps don't include this property] on 1927 on "Niles" St.	SH						Small late 20th century shed w/barn look (red & white w/gambrel roof)	Cobblestone retaining wall & piers at entrance gate along Maple Rd. side of property; concrete steps
Arched front door; hipped roof front sunroom; piano window on nrth façade; massive battered chimney w/banding at top; craftsman type windows w/muntin pattern of various sized squares/rectangles	N							
Driveway access to property at East Main St.	N							
Adaptive reuse of frame stable bldg to residence w/large addition to south & small 1-story vestibule added to north side both after 1927, (per Sanborn); front gable carriage house appears on 1883 Birdseye;	N							
Doric columns on front porch; intact porch skirting & railing; 2-story corner pilasters; piano windows	B	Y	N	INT	Y	N	WF; WN; c1910 lean-to w/shed roof ; orig doors & windows intact	white picket fence
Wide double bracketed cornice w/dentils & pendants; window & door surrounds; blinds; illustrated on 1883 Birdseye; rear ell added between 1904 & 1927 (per Sanborn) NOTE: orig. FWS porch altered w/front section totally removed leaving only side (after 1927 per Sanborn)	B	Y	N	INT	Y	N	WF; WC c1870 w/sliding doors still intact (windows added); Small 1-story shed @ rear property line	
Wide cornice & overhanging eaves but brackets removed; orig. front door w/double arches; appears on 1883 Birdseye w/different roof; on 1904 & 1927 Sanborns NOTE: full front porch removed after 1927	B	Y	N	INT	Y	N	WF; WC c1870 barn w/1-story lean-to addition to south side & larger 1-1/2 story addition to north	
Pedimented front porch; pentice between 1st & second fl.; side porch enclosed; appears on 1883 Birdseye; NOTE: full front porch removed after 1927 (per Sanborn)	B	Y	N	ALT	Y	N	WF; WC w/hay door intact; o.h. door installed; 1-story addition to side for 2nd garage has false front	
False gambrel roof w/pentice; gabled entrance canopy has brackets; front bay window w/hipped pentice over tied into entrance canopy; not on Sanborn maps	G	Y	N	INT	Y	N	WF; WC garage w/ o. h. doors installed	white picket fence & gate across driveway
Cornices; window & door surrounds; front porch w/columns & hexagonal capitals; 1-1/2 side ell & 1-story rear ell appear on 1904 Sanborn; bldg on 1883 Birdseye NOTE: brackets on cornice may have been removed	G	N	N	INT	Y	N	WF; WN; c1920 small garage w/sliding doors intact	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.18-8-26	114	NORTH ST	B	SFR	DOM	SD	IT	c1870	2	SP	RE-2	N	WF	WC	VS	CL	H	SSM & A	N	N	REP	INT	FE	REP	ALT	Y	N
56.18-8-27	116	NORTH ST	B	SFR	DOM	SD	IT	c1870	2	SP	RE-2	N	WF	WC	COM	CL	H	SSM & A	N	N	INT	REP	FF	REP	ALT	Y	N
56.18-8-28	118	NORTH ST	B	SFR	DOM	SD	IT	c1870	2	SP	RE-2	NH	WF	WC	VS	CL-S	H	A	N	N	REP	REP	FE	REP	ALT	Y	N
68.5-5-6	103	PARK PL	B	CUL	R/C	THR	TR	c1925	1	O	SE-1	H	M	B	N	PC	S	SSM	N	N	ALT	REP	N	na	INT	Y	N
68.5-5-5	105	PARK PL	B	C	C/T	RES	GR	c1850	2	CP	RE & SE	H & NH	WF	WC	MS	CL	G	SSM	N	N	INT	INT	FF	REP	INT	Y	N
68.5-5-4	107	PARK PL	B	MFR	U	-	SE	c1875	2	O	RE-1	H	WF	U	VS	CL	H	A	N	N	ALT	ALT	N	na	ALT	Y	N
68.5-5-3	109	PARK PL	B	C & R	C/T	SPE	CR	c1910	2	O	SE-2	H	WF	WC	VS partial	CL	FG	A & SSM	N	N	MIX	REP	F	ALT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Window surrounds; 1-story bay on south side added between 1904 & 1927 (per Sanborns); orig. no front porch; appears on 1883 Birdseye; NOTE: small bay window on front added late 20th century	B	Y	N	INT	Y	N	WF; WN; c1870; hay door & sliding door intact	
Appears on 1883 Birdseye; NOTE: all distinguishing architectural decor. removed or covered over; full front porch removed after 1927 (per Sanborn) & replaced w/front entrance canopy	B	N	N	ALT	Y	N	WF; WN c1900 barn w/gambrel roof; o.h. doors installed	
Doric columns on front porch; turned columns on side porch; on 1883 Birdseye; 1-story north side ell added after 1927 (per Sanborn)	B	Y	N	ALT	Y	N	WF; WC; c1870; addition w/shed roof to north side, 1-story garage addition to front	
Wide classical revival cornice band on on front façade; crenolated parapet wall; concrete headers & lintels on doors & window; lozenge shaped leaded galss window; on 1929 Sanborn labeled as "Park Theater-Movies"; NOTE: marquee added later c1940	N							
Fluted Doric columns w/dentiled frieze; heavy corner pilasters & cornice; window surrounds on 1st fl.; entrance door surround w/transom & sidelights; wood shingles on gable ends; appears on 1883 Birdseye; & 1866 map labels as "C. Courter"; 1887 Sanborn labels the building as a dwelling & shows 3 rear ells of 2, 1-1/2 & 1 stories; NOTE: "Established 1802" must be referring to date of earlier bldg on site since architecturally this bldg dates to c1850	N							
Significantly altered early bldg of which orig. use is unknown (Sanborn maps not labeled); on 1883 Birdseye; 1887 Sanborn notes "French Roof" (mansard) & shows 1-story rear ell & 1-story square access. bldg @ rear; 1892 Sanborn shows front projecting pavilion & additions to accessory bldg toward main bldg.; 1904 Sanborn shows portion of front pavilion removed & 1-story side ell added; 1927 Sanborn labels as "Auto Repair Shop"	SH	Y	N	INT	Y	N	Small sq. WF shed w/mansard roof on a concrete slab; c1975; generally intact w/minor alterations of windows & door	
Pedimented front gable w/attic fanlight window, large 2nd story overhang w/triple columns at corners; 2-story side ell w/bracketed cornice, storefront façade; arched attic window canopy in rear gable end; 2nd story 2-over-2 windows intact; not on 1883 Birdseye, 1887, 1892 or 1904 Sanborns; appears on 1927 Sanborn w/side ell labeled "Lumber" & 1-story rear ell; 2nd story on RE not shown (later than 1927); NOTE: front porch has been radically altered with iron posts replacing orig. support posts	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																												
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan	
ROW	-	PARK PL	ST	BRI	TRA	RD	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na
68.5-5-16	111	PARK PL	B	MFR	DOM	SD	CR	c1860	2	O	RE	H & NH	WF	WC	WC	CL	FG	SSM	N	N	MIX	REP	FF	REP	INT	Y	N	
68.5-5-15	113	PARK PL	B	MFR	DOM	SD	CC	c1915	2	O	RE-2	N	WF	WC	N	CL	FG	SSM	N	OR	INT	INT	FF	INT	INT	Y	N	
68.5-5-14	115	PARK PL	B	SFR	DOM	SD	CR	c1910	2	O	N	N	M & WF	B SS & STU	N	CL	H	A	N	OR	INT	INT	FWS	INT	INT	Y	N	
68.5-5-2	117	PARK PL	B	MFR	DOM	SD	GR	c1850	2	CP	RE-2 SE-2	N	WF	WC	N	CL	G & FL	SSM	N	N	INT	INT	S	INT	INT	Y	N	
68.5-5-13	121	PARK PL	B	MFR	DOM	SD	DC	c1930	2	O	SE-1	N	WF	WC	N	CL	G	A	N	N	INT	INT	FE	INT	INT	Y	N	

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Small bridge over Mill Creek south of Center Park, betw. bldgs at 109 & 111 Park Place; unmatched wood side railings, reinforced by steel members behind; a bridge was probably in this location from the earliest settlement as Park Place is shown as already developed on 1866 map; also shows on subsequent Birdseye & Sanborns	N							
2-story front porch w/turned columns & decor. braces (front porch is a historic addition); possibly on 1866 map as "D.A.S."; bldg. appears on 1883 Birdseye; 1887 Sanborn shows no porch, small 1-story ell and much shorter bldg; 1892 Sanborn shows 1-story front porch & exterior stair to 2nd fl. up east side; 1927 Sanborn shows 2-story rear porch (enclosed after this date) NOTE: ; gable end & 1st floor front façade has been resided w/wider clapboards	N							
Paneled railings & turned columns on 2-level front porches; transoms on front windows; side 2-story bay (west side); not on 1883 Birdseye or 1887, 1892 or 1904 Sanborns; 1927 Sanborn shows bldg w/open 2-level porches both front & back NOTE: rear porches enclosed after 1927	N							
Porte cochere w/pediment; projecting gables w/pediments; Doric columns, dentiled frieze & pediment on curved wrap-around front porch; limestone headers & lintels on 1st fl. windows; stained glass transom, oval & chimney windows; leaded glass windows; 2-story bay window on west side bisected by a massive chimney w/window & limestone caps; cobblestone treatment on porch foundation; 1st shows up on Sanborn map in 1927, labeled "Vend.1st" (vendor 1st fl?)	B	Y	N	INT	Y	N	WF, WC 1-story barn c1910 w hay door & sliding door intact	
Greek cornice; large corner pilasters; window & door surrounds; transom & sidelight on entrance door window blinds; side porch w/hipped roof; orig. chimneys; on 1866 map "Dr. L. Cross"; on 1883 Birdseye; on 1887 w/side ell	B	Y	N	INT	Y	N	WF; WC c1850 2-story barn w intact hay door	
False gambrel roof w/pentice betw. 1st & 2nd fls.; fluted pilasters flanking front entrance; pediment w/brackets on front entrance porch ; bracketed 1st fl. pentice; attic fanlights in gable ends; not on 1883 Birdseye or any of the Sanborns	G	Y	N	INT	Y	N	WF; WC c1930; fanlight over single garage door	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-5-12	123	PARK PL	B	MFR	DOM	SD	U	c1915	2	O	FE RE SE	H & NH	WF	WC	COM	CL	FG	A & SSM	N	N	ALT	ALT	FE	REM	ALT	Y	N
56.18-1-9	105	PROSPECT ST	B	SFR	DOM	SD	QA	c1895	2	O	N	NH	WF	WC	N	CL	H	S	Y	N	INT	INT	FWS	REP	INT	Y	N
56.18-1-8	111	PROSPECT ST	B	MFR	DOM	SD	QA	c1895	2	O	RE-1	N	WF	WC & WS	N	CL	H	S	N	OR	INT	INT	F	ENC	INT	Y	N
56.18-1-7	113	PROSPECT ST	B	SFR	DOM	SD	QA	c1895	2	O	N	H	WF	WC	N	CL	H	S & SSM	Y	N	INT	INT	FWS	INT	INT	Y	N
56.18-1-6	119	PROSPECT ST	B	SFR	DOM	SD	QA	c1895	2	O	N	N	WF	WC & WS	N	CL	H	A	Y	N	INT	INT	FWS & S	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Simple single family dwelling blt in the Craftsman period has been significantly altered with several additions to the north side; remnants of orig. front door surround on west side remain; doesn't appear on a Sanborn map until 1927, this shows simple gable end house facing Veterans drive w/small front entrance porch & 1-story rear ell off the SE corner	N							
Highly decorated Queen Anne (similar to 119 Prospect); iron cresting on projecting gables & top of hip roof; 3-story octagonal tower w/fish scale shingles, bd & batten cladding, pentice at top of 2nd fl.; bd & batten banding betw. 2nd fl. & attic; multi-paned colored glass in upper story & attic windows; banding; 2-story side bay windows w/decor. brackets; oval windows on east facade (altered); not on 1883 Birdseye; early Sanborns do not show properties along Prospect; 1st illustrated on 1927 Sanborn; NOTE: exterior stair to 2nd floor a late 20th century addition	B	Y	Y	INT	Y	N	WF; WN & BB siding & banding on c1895 barn; gable roof w/dormer; hay door has been replaced w/window; barn doors probably altered early	
"Widow's walk" on top of hip roof; Venetian attic window w/dentils; pedimented gable dormer; modillions; 2-story bay windows on front & west sides; oval stained glass window on front façade; decor. shingles on lower portion of bldg & front porch; not on 1883 Birdseye; early Sanborns do not show properties along Prospect; 1927 Sanborn shows current footprint; NOTE: front porch enclosed w/glazing	B & S	Y	Y	INT	Y	N	WF; WC 2-story barn c1895 w/hay door, windows & DGEVS/dove cote intact; also a small 1-story shed behind that appears to be a remnant of a larger "Green Ho." as labeled on the 1927 Sanborn map	
Decor. verge boards w/bracing & brackets; rounded wrap-around front porch w/spindled frieze & scroll sawn skirting; false window w/blinds; banding; board & batten cladding in gable ends w/inset angled bead board; not on 1883 Birdseye; early Sanborns do not show properties along Prospect; on 1927 Sanborn; NOTE: 1-story lean-to on east side c1920	B	Y	N	INT	Y	N	WF; WN siding; c1895; hay door & window intact; o.h. doors installed; on 1927 Sanborn	
Highly decor. Queen Anne (very similar to 105 Prospect); 3-story octagonal tower w/fish scale shingles & bd & batten siding, roof finial; projecting hip & gable roofs, w/decor. shingle work; iron cresting at ridge; decor. verge boards & brackets; attic window surround; bd & batten & simple banding; 2 front porches, both w/turned columns, dentiled cornices, spindled friezes; winged pedimented porch entrance on curved wrap-around porch; not on 1883 Birdseye; early Sanborns do not show properties along Prospect; 1927 Sanborn shows current footprint;	B	Y	N	INT	Y	N	Large WF; WN; cross gable c 1895 barn; intact hay door & windows; o.h. door installed; on 1927 Sanborn map	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																												
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan	
56.18-1-5	123	PROSPECT ST	B	SFR	DOM	SD	QA	c1915	2	O	RE-1	N	WF	WC	N	CL	H	A	N	OR	INT	INT	FF	INT	INT	Y	N	
56.18-1-4	125	PROSPECT ST	B	MFR	DOM	SD	GO	c1885	2	UPW	RE-2 & SE-1	H	WF	WC & BB	N	CL - B	CG	S	N	N	MIX	INT	F	INT	INT	Y	N	
56.18-1-3	131	PROSPECT ST	B	SFR	DOM	SD	BUN	c1915	1	SQ	RE	NH	WF	WC WS	VS	RFC	G	A	N	OR	INT	INT	FF	ENC	ALT	Y	N	
68.6-1-15	136	RAILROAD AVE	B	C	C/T	RES	QA	c1890	1	O	SE-1	NH	WF	WC		CL	H	A	N	N	ALT	ALT	N	na				
68.6-6-11	FAIR GRNS	SOUTH GRAND ST	B ST SI	REC	F/C	FR	na																					
68.6-6-23	180	SOUTH GRAND ST	B	MFR	DOM	MD	CR	c1910	2	O	N	N	WF	WC	VS	CL	H	S	N	OR	INT	INT	F & R	INT	INT	Y	N	

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Octagonal footprint (cut corners at front); board & batten banding under eaves; leaded glass transoms in several windows w/diamond paned pattern; false window w/blinds; Jerkin head dormer w/multi-paned colored glass attic windows; beaded joints on limestone foundation; not on 1883 Birdseye; early Sanborns do not show properties along Prospect; 1927 Sanborn shows current footprint;	G	Y	N	INT	Y	N	Small 1-story c1915 garage w/Jerkin head gable; WF, WC, intact except o.h. door installed; 1927 Sanborn cuts off garage footprint but notes: "35' to frame Auto Ho."	
Board & batten decor. in gable end & under eaves; decor. banding between 2nd fl. & attic; 1-story bay windows on front, east & west sides; multi-paned colored glass attic windows; front porch has turned columns, pendant decorations on cornice & scroll sawn braces (may be missing railings); not on 1883 Birdseye; early Sanborns do not show properties along Prospect; 1927 Sanborn shows current footprint NOTE: windows in rear have been replace, maybe added	G & S	N	N	ALT	Y	N	c1925 WF; vertical wood siding w/banding; appears altered; Also WF shed matches house w same decoration & slate roof	
Wood shingles on posts of formerly open porch; on 1927 Sanborn, but no garage shown NOTE: vinyl siding has covered up orig. cladding which may have been either wood shingles or wood clapboard or a combination of both; breezeway addition connecting garage w/house is probably not historic	G	N	N	INT	Y	N	c1930 intact WF, WN 2-story garage	
Former RR station which was rebuilt between 1892 & 1904; small brick bldg. was partially demolished & replaced w/2 bldgs, the station & a detached restaurant under 1 roof canopy; space between station & restaurant was infilled after 1927 (Sanborns); large wood brackets support wide roof eaves on north, west & south sides; eyebrow windows on all 4 sides of center roof; cupola w/vents; wood gutter w/reverse curved brackets above NOTE: Now adapted for restaurant/bar use; chimney on west side partially covers eyebrow window on this side	N						NOTE: freestanding coolers & hvac units on south side of bldg enclosed w/in privacy fencing	
Cobleskill Sunshine Fair Grounds SEE SEPARATE LISTING OF BLDGS (END)	O							
Front porch w/Roman columns, pediment, turned balustrades, craftsman-like skirting; double projecting front gables; carved rafter ends; window blinds; hipped roof dormer w/multi-paned colored glass attic windows; leaded glass transoms over front windows; front doors have large glass panels; none of the Sanborns include this property; not on 1883 Birdseye	G	N	N	INT	N	N	WF, VS double garage w/2 indiv. o.h. doors; dates to mid-to late-20th century	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.6-5-12	181	SOUTH GRAND ST	B	SFR	DOM	SD	QA	c1890	2	O	RE-1	N	WF	WC	VS	CL	H	A	N	OR	REP	INT	FF	INT	ALT	Y	N
68.6-5-11	183	SOUTH GRAND ST	B	MFR	DOM	SD	QA	c1885	2	O	RE-1	NH	WF	WC & WS	N	CL	CG	S	Y	OR	INT	INT	FF	INT	INT	Y	Y
68.6-6-22	184	SOUTH GRAND ST	B	SFR	DOM	SD	CC	c1920	2	O	SE-1	N	WF	WC	N	RFC	FG	A	N	OR	INT	INT	F	INT	INT	Y	N
68.6-6-21	186	SOUTH GRAND ST	B	MFR	DOM	MD	CR	c1910	2	O	RE-2	N	WF	WC	MS	RFC	H	S	N	OR	MIX	INT	F & F	INT	INT	Y	N
68.6-5-10	187	SOUTH GRAND ST	B	MFR	DOM	SD	QA	c1890	2	O	N	NH	WF	WC	N	CL	H	A	Y	N	MIX	INT	FE	INT	INT	Y	N
68.6-5-9	191	SOUTH GRAND ST	B	SFR	DOM	SD	CLR	c1890	2	TH	RE-1-1/2	NH	WF	WC & WS	N	CL	FG	S & SSM	Y	N	INT	INT	FF	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Steeply pitched gabled front dormer w/oval window; 2nd story bay window over the front porch/entrance; Doric columns on porch; rectilinear lattice porch skirting; porch partially glazed; NOTE: it appears that much of the orig. decor. trim has been lost or covered over w/vinyl siding	G	N	N	INT	N	N	Mid- to late-20th century WF double garage	
Square tower w/hip roof, slate shingles & weather vane atop; mansard banding betw. 1st & 2nd fl.s; paneled headers on 2nd fl. windows; multi-paned colored glass attic windows; decor. gable end w/curved battens over clapboard; fanlights in gabled dormer on south side; round port hole window on north facade; rectilinear lattice porch skirting; spindled frieze on porch; doesn't appear on 1883 Birdseye or any Sanborn Maps; NOTE: iron fire escape on north facade not historic; endangered by poor maintenance (front porch falling off)	B	Y	N	INT	Y	N	WF; WC 2-story barn w/hay doors, orig. barn doors & windows intact; c1885	
Jerkin head front gable & front entrance canopy; carved, exposed rafters/joists & brackets on sun porch & front entrance canopy; board & batten on gable end; shed roof dormer on south side; door & window surrounds; not on 1883 Birdseye; 1927 Sanborn shows edge of house	G	Y	N	INT	Y	N	WF; WC double garage, c1920 (o.h. doors may have been modified)	Large lot
Early Duplex; two matching oval stained glass windows on front; Doric columns, glazing on 2 separate front porches; projecting pavilion w/gable & Venetian like attic window w/colored glass & quarter-circle side windows; 1927 Sanborn shows duplex + 2 barns behind; NOTE: decora. architectural elements have been lost or covered over (as indicated by barn)	B	Y	N	INT	Y	N	2-story WF, WC barn divided for 2 units; sliding doors; hay door & 2 windows still intact	
Highly decorated Queen Anne w/projecting front gable; projecting side pavilions w/box bay windows; door & window surrounds; decorative banding w/bullseye design; board & batten on upper 1/2 of 2nd fl.; scroll sawn braces; blinds on false windows; front porch w/pediment, scroll sawn insert & spindled frieze; multi-paned colored glass windows; on 1927 Sanborn NOTE: 2-car garage added off NE corner of house	N							Bluestone walkways
Front porch partially glazed, w/Doric columns & scroll sawn skirting; turned columns on rear porch; decor. shingled gable end; decor. exposed joists; decor. brackets at corners of eaves; on 1927 Sanborn w/barn; NOTE: chimney added to front of house in mid- to late 20th century	B	Y	N	INT	Y	N	2-story c1890 front gable, WF, WC single span barn w/hay door & sliding door intact	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.6-6-20	192	SOUTH GRAND ST	B	MFR	DOM	SD	GO	c1880	2	O	RE-1	H	WF	WC	B	CL	H	A	Y	N	INT	INT	FWS S	INT	INT	Y	N
68.6-5-8	193	SOUTH GRAND ST	B	MFR	DOM	MD	IT	c1870	2	O	RE-2	NH	WF	WC	N	CL	FL	U	N	N	INT	INT	FE	REP	INT	Y	N
68.6-6-19	194	SOUTH GRAND ST	B	MFR	DOM	SD	GO	c1880	1-1/2	O	RE -2	H	WF	BB	VS	CL	G	A	N	N	MIX	INT	FE & S	REP & ENC	ALT	Y	N
68.6-6-18	196	SOUTH GRAND ST	B	MFR	DOM	SD	IT	c1880	2	O	RE-2	NH	WF	WC	VS	CL	FL	U	N	N	INT	INT	FWS	INT	ALT	Y	N
68.6-5-7 & 68.6-5-3	197	SOUTH GRAND ST	B	MFR	DOM	SD	IT	c1870	2	UPW	SE-2	NH	WF	WC	N	CL	H	A	N	N	INT	INT	FF	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES							Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan	Description		
Decorated verge board; fluted double brackets; door & window surrounds; carved exposed joists; projecting gables have decor. spandrels, brackets & screens, board & batten siding w/bulls-eye banding, clipped corner shingles above; arched attic windows w/scroll sawn decor. surrounds; front porch w/spindle frieze, scroll sawn braces & skirting; 1-story box bay w/shed roofed balcony above on north side; front bay window w/engaged front porch; NOTE 1-story shed roofed lean-to @ NE corner not on 1883 Birdseye; [1887, 1892 & Sanborns do not include this property]; 1904 Sanborn shows edge of barn; on 1927 Sanborn	B & S	Y	Y	INT	Y (both)	N	2-story c1880 WF, WC barn w/scroll sawn header over door; 4 multi-paned windows, hay door & sliding doors intact; decor gable end vent screen; Plus a 1-1/2 story WF, WC accessory bldg. which the 1927 Sanborn shows behind barn at north property line (now moved to south side of property behind house), also c1880 w/added chimney, doors & windows intact, SSM roof		
Heavy double bracketed cornice w/pendants; small bracketed headers on windows; on 1883 Birdseye, 1982 Sanborn does not include property but notes: "60' to fr. dwg." - this house; NOTE: front first floor windows have lost headers; orig. full front porch has been removed & replaced with gable roofed front entrance porch; roof addition/alt. to rear ell from flat to shed roof & infill of 1-story shed roof lean-to at SW corner	N								
Steeply pitched gable roof w/projecting center pavilion also w/steep gable; on 1883 Birdseye; 1892 Sanborn shows only edge of bldg; 1904 Sanborn shows 1-story rear ell w/1 story porches on both no. & so. sides, no garage or barn; 1927 Sanborn shows bldg w/1-story garage labeled "Monument Works" NOTE: classic Gothic revival detailing has been removed or covered over w/vinyl siding, rear porch has been enclosed; rear lean-to added in 20th century	G	N	N	ALT	Y	N	WF; vinyl sided c1925 small barn that fits the footprint on the 1927 Sanborn	Bluestone front walkway	
Roman columns, balustrades on front porch w/early glazing; on 1883 Birdseye; 1887 Sanborn does not incl. property; 1892 & 1904 Sanborns show small front porch; 1927 Sanborn show full front porch wrapping around to south side	B	Y	N	INT	Y	N	WF; WC c1880 barn w/hay door, sliding door & windows intact		
Double bracketed cornice w/pendants; door & window surrounds; blinds; on 1883 Birdseye; 1892 Sanborn shows footprint w/bow window; 1927 Sanborn, no 2nd front porch	B	Y	N	INT	Y	N	Barn on separate lot on Brookside Avenue; large WF, WC & WN barn w/cross gable roof; 2 hay doors still intact; single o.h. door installed; 1927 Sanborn has barn labeled as "Stove Repairing & stge."		

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																												
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan	
68.6-6-17	198	SOUTH GRAND ST	B	MFR	DOM	SD	CLR	c1880	2	UPW	RE-1-1/2	NH	WF	WC	N	CL	CG	A S & SSM	N	N	REP & ALT	ALT	FWS	REM	ALT	Y	N	
68.6-5-6	199	SOUTH GRAND ST	B	SFR	DOM	SD	IT	c1870	2	O	RE-1	N	WF	WC	N	CL - C	H	SSM	N	N	REP	INT	FF & R	INT / REP	INT	Y	N	
68.6-6-16	202	SOUTH GRAND ST	B	MFR	DOM	SD	IT	c1870	2	O	RE-1	H	WF	WC	VS partial	CL	FL	SSM & U	N	N	INT	?	FF	ENC	INT	Y	N	
68.6-5-5	203	SOUTH GRAND ST	B	MFR	DOM	SD	SE	c1880	2	UPW	RE-2 (2)	H & NH	WF	WC	MS	CL	M	WS	N	OR	MIX	MIX	FWS & F	INT	INT	Y	N	
ROW	-	SOUTH GRAND ST	ST	BRI	TRA	RR	na	c1938	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na
68.5-5-7	PKG	SOUTH GRAND ST	ST	PKG	DOM	SD	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na
68.6-1-1	214	SOUTH GRAND ST	B	MFR	C/T	DEP	CR	c1860	2	TH	RE-2	H	WF	WC	COM	CL	FG	SSM	N	N	INT	INT	F & S	INT & ENC	INT	Y	N	
68.5-5-8	215	SOUTH GRAND ST	B	C	IND	MFG	U	c1925	1	O	N	H	M	STU	N	PC	FL	U	N	N	INT	REP	N	na	INT	Y	N	

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
On 1883 Birdseye; 1887 doesn't show property; 1892 & 1904 Sanborns show upright & wing footprint w/2 small side porches, 1-1/2-story rear ell, 2-story barn; 1927 Sanborn shows wrap-around front porch & extended south side porch, 2 additional outbuildings; NOTE: Any architectural details orig. to bldg have been removed; front porch has been removed & replaced w/small canopy front entrance porch w/modern materials	B	Y	N	ALT	Y	N	Radically altered 2-story c1880 barn that was once WF w/WC; contributing because form can still be read	
Front porch w/Doric columns; sawtooth & wave patterns on cornice; window headers & door surrounds; front porch screened in early 20th century; on 1883 Birdseye; on 1892, 1904 & 1927 Sanborns	B	Y	N	INT	Y	N	WF: WC; c1870 barn w/ hay door intact; single o.h. door installed	
Wide cornice; bracketed eaves (modillions); window surrounds; corner boards; stained glass transom in side window; on 1882 Birdseye; on 1887 & later Sanborns; NOTE: rear enclosed stairway to 2nd fl. c. early 20th century; front porch enclosed w/1-over-1 sash windows relatively early	B	Y	N	INT	Y	N	WF: WC; c1870 barn w/early 2-story addition to north side; hay doors & windows intact; 3 o.h. doors installed	
Window headers; leaded glass transom window on 1st fl. w/dentil trim; pedimented front entrance porch; curved pediments and dormers on mansard roof w/scroll sawn insert; on 1883 Birdseye; 1892 Sanborn indicates it is a single family dwelling, does not show front porch wrapping around to side, 2-story rear ell (north side), 1-1/2-story rear ell w/1-story rear ell on south; 1904 Sanborn, still single family, no wrap-around porch; 1927 Sanborn shows wrap-around porch on north and east, 2-family dwelling	N							
Railroad and roadway overpass over South Grand St. between Main St. & MacArthur Ave.	N							
Village Parking Lot; vacant on 1887 Sanborn; 1 WF 1-story dwelling on 1892, 1904 & 1927 Sanborns	N							
Scroll sawn porch skirting; Classical Revival porch enclosure occurred c1900- fanlights over windows; probably the "store" labeled on 1866 map; on 1883 Birdseye; 1887 Sanborn labeled as "Gro." (with livery behind on same lot); 1892 Sanborn, "Vac. S" [Vacant]; 1904 & 1927 Sanborns, "Dwelling"	N							
Concrete headers on windows & doors; quoined corners w/formed concrete @ west edge w/darker cinderblocks on east side; not on 1904 Sanborn; on 1927 Sanborn, labeled as "Monument Works"; concrete slab on east side may indicate loading dock(?)	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5.5-19	PKG	SOUTH GRAND ST	ST	PKG	DOM	SD	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	N	N
68.6-1-2	216	SOUTH GRAND ST	B	C & R	DOM	SD	CR	c1880	2	UPW	SE-2 & RE-2	NH	WF	WC	AS partial	CL	CG	SSM & A	N	N	MIX	REP	FF	INT	INT	Y	N
68.6-1-3	220	SOUTH GRAND ST	B	MFR	DOM	SD	IT	c1880	2	SQ	RE-1	NH	WF	WC	VS	CL	H	SSM	N	N	MIX	ALT	FF	ENC	ALT	Y	N
68.6-1-4	222	SOUTH GRAND ST	B	MFR	DOM	SD	SE	c1870	2	UPW	RE-2 SE-2	H	WF	WC	N	CL	M	WS	N	N	INT	INT	F	ENC	INT	Y	N
68.6-1-5	224	SOUTH GRAND ST	B	C & R	DOM	SD	IT	c1895	2	SP	RE-2 SE	NH	WF	WC	N	CL	FL	SSM	N	N	REP	ALT	FF	ALT	ALT	Y	N
68/6-3-12	111	SPRING ST																									
56.17-8-19	105	UNION ST	B	C	U		CR	c1900	2	O	RE-2	H	WF	WN	AS & W	U	F & S	SSM	N	N	ALT	ALT	N	na	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Cobleskill Merchants Bureau Parking Lot; Improved w/30-degree angle stalls & trees around edges; lot was vacant until after 1904; 1927 Sanborn shows a 2-story brick house, a 2-1/2-story store & a WF wood shed	N							
Front porch has turned columns, scroll sawn braces & balustrades; door & window surrounds; not on 1866 map; on 1883 Birdseye; 1887 Sanborn, "Dwelling" NOTE: exterior stairway to 2nd floor added c late 20th century	N							
On 1883 Birdseye; 1892, 1904, 1927 Sanborns label as "Dwelling"; NOTE: Original brackets removed & other details lost or covered over with vinyl siding; front porch enclosed w/modern horizontal windows used;	N							
Door & Window surrounds, double bracketed cornice; eyebrow detail on front roof eave; small pediment on sunroom (enclosed porch); orig. porch w/ storefront windows still has brackets in place as does the front 1-story bay window; on 1883 Birdseye; on 1887 Sanborn, small porch in front of side ell only(north side); 1892 Sanborn, 2nd front porch added to main bldg (south side); 1904 Sanborn, rear ell added; 1927 Sanborn, 2 rear ells combined & exterior stair added; NOTE: two front porches enclosed; rear 2nd floor addition, exterior stairway enclosed c late 20th century	B	Y	N	INT	Y	N	WF; WN c1870 w/intact windows	
Window surrounds; decorative front brackets w/scroll sawn sides; paneled cornice; doesn't show up until 1904 Sanborn as "Dwelling"	N							
SEE 642 MAIN ST	-							
Front added to an older brick bldg; Colonial revival remodeling c1940 or 1950 w/storefront treatment that wraps around side of bldg; very wide cornice w/dentils, door surround w/dentils & transom; alternating widths of wood novelty siding, vertical wood kneewall on 1st fl.; 48-paned windows on 1st fl. front & side; shutters on 2nd floor windows w/ panels underneath w/Chinese lattice; front door has 8 panels--2 w/Greek frets & reverse fret; not on 1883 Birdseye or 1887, 1892 Sanborns; 1904 Sanborn shows a 2-story carriage house/livery well set back from Union St.; 1927 labels expanded bldg as "Auto Repairing" w/multiple wings 1, 1-1/2, & 2 stories in height & still set back from Union St.	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
56.18-7-1.2	110	UNION ST	B	LIB	EDU	SCH	CR	1884	2	O	RE-2 (3)	H	M	B	N	CL	H	S & A	N	N	MIX	INT	N	na	INT	Y	N
56.18-7-23	108	UNION ST	B	C	C/T	WHS	U	c1870	2	SQ	SE-1 (2) RE	H	WF	U	WC	U	CG	A	N	N	ALT	ALT	N	na	ALT	Y	N
56.17-8-8	137	UNION ST	B	MFR	DOM	SD	IT	c1870	2	O	RE-2	NH	WF	WC	N	CL	H	A	N	N	REP	REP	F S R(2)	REP	INT	Y	N
56.17-7-10	145	UNION ST	B	SFR	DOM	SD	CA	c1940	1	O	RE-1	N	WF	WS	N	C	G	A	N	OR	INT	INT	N	na	INT	Y	N
68.5-4-24	117	VETERANS DR	B	C	C/T	FIN	DC	1960	1-1/2	O	RE	N	M	B	N	PC	G	S	N	N	INT	INT	S	INT	INT	Y	N
68.5-3-38	104	WASHINGTON AVE	B	SFR	DOM	SD	QA	c1910	2	O	N	N	WF	WC	N	CL	H	S	N	N	INT	INT	FWS	ALT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Endan	Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Description			
Original school adapted for use as the "Community Library"; projecting front bay; substantial cornice; brick corbeling; pilasters; fanlight over orig. double front door; arched windows w/9-over-9 sashes; engaged chimney on south side; although cornerstone states 1884 date, the bldg shows up on 1883 Birdseye; 1887 Sanborn shows public school with "I" footprint; 1892 Sanborn notes that the school is "Heated by Furnaces"; 1904 Sanborn shows rear ell addition off east side (matches style of orig. bldg)	N								Stone retaining wall along west side of property
The building has been substantially altered, resided & reconfigured over the years; orig. associated with the United States Hotel; appears on 1883 Birdseye; 1887 Sanborn labels: "P. Dwelly's Bottling Works Ice House"; 1904 Sanborn shows an expanded rectilinear footprint; 1927 Sanborn shows building back to orig. sq. footprint (this could indicate a replacement bldg); NOTE: the 3 ells off the north, east & south sides occur after 1927, as well as entrance vestibule addition on west side	N								
Wide overhanging eave & bracketed cornice w/2 sizes of brackets; window & door surrounds; gable canopy over Chapel St. entrance; on 1883 Birdseye; 1887 & 1892 Sanborns do not incl. this property; 1904 Sanborn shows single dwelling w/front porch on Union & smaller porch facing Chapel; 1927 Sanborn shows duplex w/rear porches added	N								
Dormers; wood shingle siding; not on 1927 Sanborn map									
Despite being a later bldg, this is found to be contributing because of its outstanding adaptation of a historic style; parapet gables capped w/stone & incorporating massive chimneys; wide fascia board; entrance on gable end w/curved porch roof ; round windows in gable ends; rear wall inset from roof line; ivy covered bldg.; metal multi-paned windows; rear drive-thru window incorporated in rear ell	N								
Decora. gable ends w/shingles; wrap-around front porch w/Doric columns, modillions & scroll sawn skirting; oval stained glass window 1st floor front façade; 2-story bay window w/projecting gable over; door & window surrounds; not on 1904 Sanborn; NOTE: 1927 Sanborn shows that orig. front porch wrapped around both sides of house w/rounded corners (northern portion since removed)	G	N	N	INT	Y	N	Early WF, WC single stall garage; c1915, hip roof; doors intact		

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-39	106	WASHINGTON AVE	B	SFR	DOM	SD	QA	c1910	2	O	N	N	WF	WC	N	CL	H	S	N	N	INT	U	FWS & S	INT	INT	Y	N
68.5-2-23	107	WASHINGTON AVE	B	MFR	DOM	MD	QA	c1910	2	SQ	N	N	WF	WC	N	CL	H	A	N	N	REP	INT	FE & S	INT	INT	Y	N
68.5-3-40	108	WASHINGTON AVE	B	SFR	DOM	SD	QA	c1910	2	O	N	N	WF	WC	N	CL	H	S	N	OR	INT	INT	FF	INT	INT	Y	N
68.5-2-22	109	WASHINGTON AVE (also 110 Hidden Lane)	B	SFR	DOM	SD	QA	1894	2	O	N	N	WF	WC	N	CL	H	S SSM & A	Y	N	INT	INT	FWS	ALT	INT	Y	N
68.5-3-41	112	WASHINGTON AVE	B	MFR	DOM	SD	GO	c1890	2	SQ	N	N	WF	WC	N	CL	H	SSM & A	Y	N	MIX	INT	FF	ALT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
2-story bay windows front & side w/pedimented projecting gables; curved wrap-around porch w/Roman columns & bracketed cornice; small side porch at NE corner of house; stained glass transom windows on 1st & 2nd fls.; multi-paned colored glass in rectilinear tripartite attic window; beaded joints in limestone foundation; not on 1904 Sanborn; 1927 Sanborn shows current footprint	B	Y	Y	INT	Y	N	WF; WC; 2-story c1910 barn w/hay door, sliding doors & attic window all intact	
Window & door surrounds; two 2-story bay windows on front façade, pedimented projecting gable ends above w/rectilinear tripartite attic windows; 2-story bay window on south side; 2-story porch on north side is orig.; not on 1904 Sanborn; 1927 Sanborn shows duplex w/present footprint	B	N	N	INT	Y	N	WF; WC; c1890 2-story barn w/hay doors & sliding door intact; this barn was associated w/property at 435 West Main Street on 1904 Sanborn	
Bracketed cornice; 2-story front bay window w/pedimented projecting gable w/brackets below & arched attic window; 2-story bay on south side w/projecting pedimented gable, brackets, circular attic window; box oriel on north side w/projecting pedimented gable; dentils on dormer cornice, porch cornice & gables pediments; dormer has hip roof, massive chimney constructed of blonde brick; window surrounds; front door surround w/sidelights; diamond paned attic windows; not on 1904 Sanborn; 1927 Sanborn shows present footprint	G	N	N	INT	Y	N	WF; WC 1-story hip roofed double-stall garage; probably added onto & reroofed dating to mid-20th century; 1927 Sanborn shows small 1-stall garage	
Round 2-story tower w/conical roof, bracketed & dentiled cornice; projecting gables w/highly decor. scroll sawn vent screens; decor. exposed rafters; 2-story bay window on south side; door & window surrounds; board & batten on gable ends & under eaves; dochr. banding betw. 2nd fl. & attic; circular stained glass window on north side; Doric columns on side porch, sleeping porch/enclosed balcony above; NOTE: missing large portion of orig. wrap-around porch (per 1904 & 1927 Sanborn maps) & orig. Doric columns replaced w/current sq. ones	B	Y	N	INT	Y	N	WF; WC, 2-story 1894 barn w/projecting gable broken eave dormer w/hay door; slate roof; cupola; doors & windows appear intact from Washington Ave - though bldg has been adapted for residential use	
Blt. as a duplex; board & batten cladding under roof eaves & projecting gables; false windows w/blinds over front entry; fanlight attic windows; decor. gable end vent screens w/pendants; NOTE: some alterations: full front porch (on 1904 & 1927 Sanborns) has been replaced w/Classic Revival/ Craftsman style front entrance porch; other architectural components window surrounds such as appear to be lost, roof may have been replaced;	G	N	N	INT	N	N	Mid- to late-20th century WF WC 2-stall garage; 1904 Sanborn shows a very small shed behind house; 1927 Sanborn show no accessory bldg.	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-2-21	113	WASHINGTON AVE	B	MFR	DOM	SD	GO	c1890	2	UPW	SE-2	H & NH	WF	WC	N	CL	CG	A & SSM	N	OR	INT	ALT / REP	F	ALT	ALT	Y	N
68.5-3-42	114	WASHINGTON AVE	B	SFR	DOM	SD	GO	c1890	2	UPW	SE-2	N	WF	WC	COM	CL	CG	SSM	N	N	REP	INT	F	INT	INT	Y	N
68.5-2-20	115	WASHINGTON AVE	B	SFR	DOM	SD	GO	c1890	2	O	RE-2	N	WF	WC	N	CL	H	S	N	N	INT	REP	FE	ENC	INT	Y	N
68.5-3-43	118	WASHINGTON AVE	B	MFR	DOM	SD	GO	c1890	2	O	RE-2	H	WF	WC	N	CL	G	S	Y	N	INT	INT	FWS	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Broken eave dormers; decor. shingling in gable ends; banding; decor. window surrounds; appears on 1904 Sanborn; NOTE: Orig. front porch has been expanded out from front of building, a second story added & all enclosed after 1927	O	Y	N	INT	Y	N	WF, WC gable roof w/false front; storefront windows & double doors; c1890; appears to have been used as a manufacturing/storage facility; 1927 Sanborn labels as "Bottling Works"	
Tiered 1-story bay window on south side; decor. verge boards; spindle brackets on gable ends; bracketed cornice on side bay w/scalloped decorative edge; tall windows w/highly ornamented headers; front porch w/highly decor. frieze, column capitals; scroll sawn braces w/pendants; 1-story rear ell; 1904 & 1927 Sanborns show present bldg. footprint	B	Y	N	ALT	Y	N	WF; WN; somewhat altered 2-story c1890 barn; renovated for residential use on 2nd fl.; attic window surround intact (window replaced) exterior deck & stairway added	
Board & batten banding on upper portion of 2nd fl.; projecting gables w/decor. shingling in gable ends; decor. verge board; carved exposed rafters; 1-story box bay on south side w/scalloped decor. frieze; ; slanted wood banding betw. 1st & 2nd fls. on south side; decor. window & door surrounds; screen door looks orig.; 1904 Sanborn indicates open front porch even w/main part of bldg. also small open porch at SW corner, replaced w/1-story ell after this date; NOTE: front entrance porch in ell has been enclosed & a small entrance porch added: door, columns; fanlight window & gable canopy are late 20th century improvements; the small multi-paned window on the front facade of the enclosed porch is probably orig. to house & been reused; massive chimney on north side probably added later	B	Y	N	INT	Y	N	WF; WN; c1890 barn w/hay door intact; o.h.door	
Highly ornamented house; board & batten on attic level & gable ends; banding on north side; gable end vent screens w/medallion, scroll sawn panels, brackets & finials; decor. slate roofing; false windows w/blinds; exposed decorative rafters; front porch has modillions, unique columns; scroll sawn skirting; colored multi-paned windows; scroll sawn braces on corners of 2-story bay window on south side; 1904 shows a smaller front entry porch on north end; 1927 Sanborn shows the expanded wrap-around porch plus a small porch on the south side (since removed)	B	Y	N	INT	Y	N	WF; WC; 2-story c1890 barn w/hay door, sliding doors & attic window all intact	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-2-19	119	WASHINGTON AVE	B	SFR	DOM	SD	QA	c1890	2	O	RE-1	N	WF	WC	N	CL	H	A & SSM	N	OR	INT	INT	FWS	INT	INT	Y	N
68.5-3-44	120	WASHINGTON AVE	B	SFR	DOM	SD	IT	c1890	2	UPW	RE-1	N	WF	WC	N	CL	H	SSM	N	N	INT	INT	F	INT	INT	Y	N
68.5-2-18	121	WASHINGTON AVE	B	MFR	DOM	SD	GO	c1895	2	O	RE-1	H	WF	WC & WS	N	CL	H	SSM	Y	Y	INT	INT	F & R	INT	INT	Y	N
68.5-3-45	122	WASHINGTON AVE	B	MFR	DOM	SD	IT	c1885	2	O	RE-2	H	WF	WC & WN	N	CL	H	SSM & A	N	N	INT	INT	FF	INT	INT	Y	N
68.5-2-17	125	WASHINGTON AVE	B	SFR	DOM	SD	GO	c1885	2	O	RE-1	N	WF	WC & BB	N	CL	H	S & A	Y	OR	INT	INT	FWS	INT	INT	Y	N
68.5-3-46	126	WASHINGTON AVE	B	SFR	DOM	SD	GO	c1885	2	UPW	SE-2	N	WF	WC & WN	N	CL	CG	SSM	Y	N	INT	INT	FE	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Decorated verge boards; exposed & decor. rafters; decor. shingling on gable ends & under eaves; paneled banding betw. 1st & 2nd fls. w.vertical & slanted slats; front porch has Doric columns, dentiled cornice, scroll sawn skirting, modillions; multi-paned colored glass attic windows; beaded joints in limestone foundation; 1904 Sanborn shows squared off wrap-around porch; 1927 Sanborn shows present rounded FWS porch in place	B	Y	N	INT	Y	N	WF; WN; c1890 barn w/hay door, sliding doors & attic window all intact;	
Wide cornice; front porch has small scroll sawn braces, square columns; window & door surrounds; nice proportions; 1904 & 1927 Sanborns show same footprint as present bldg. NOTE: massive chimney added to south side; orig. brackets probably removed	B	Y	N	INT	Y	N	WF; WC 2-story c1890 barn; hay door & sliding doors all intact	
Decor. verge board; exposed curved rafters; decor. shingling in gable ends along w/truss work w/circle in lattice design vent screens paneled banding betw. 1st & 2nd fls. w/vertical & slanted slats; 1-story bay window on south side; projecting pavilion north side; front porch w/Doric columns, pediment over entrance, & partial glazing; 1904 Sanborn shows small front porch even w/front of projecting facade & 1-story rear porch off SW corner; 1927 Sanborn shows front porch extended toward street & across entire bldg. front; NOTE: rear porch enclosed w/glazing after 1927	B	Y	N	INT	Y	N	WF; WN; 2-story c1885 barn; sliding doors still intact; hay door replaced w/window; exterior stairway to 2nd fl. added (adapted & rehabed for residential use?)	
Blt. as a single family residence per 1904 Sanborn; converted to duplex by 1927 w/addition of a 2-story octagonal tower off the southwest corner of the house, a pedimented porch extension & 2nd pediment on front porch in front of new entry; revised porch has decor. scroll sawn braces; NOTE: brackets probably removed from cornice	N							
Decor. & bracketed verge boards; door & window surrounds; board & batten on upper portions of 2nd fl. & attic; front porch w/curve roof to side, decor. frieze, modillions & rope turned columns; fanlight transom on side bay; 1-story box bay window on south side w/decor. frieze; various muntin patterns in windows throughout; 1904 & 1927 Sanborns shows present footprint in place	B	Y	N	INT	Y	N	WF; WC; c1885 2-story barn; hay door intact; o.h. doors installed	
Front porch w/highly decor. scroll sawn frieze, turned columns & winged pediment; board & battens on banding between 2nd fl. & attic & decor. battens on gable ends; 1904 Sanborn shows a footprint matching present bldg.	B	Y	N	INT	Y	N	WF; WC; c1885 2-story barn w/hay door & attic window intact; o.h. door installed	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-47	128	WASHINGTON AVE	B	SFR	DOM	SD	A4	c1920	2	SQ	N	N	WF	WS	N	PC	H	A	N	N	INT	INT	FE	INT	INT	Y	N
56.17-1-2	137	WASHINGTON AVE	B	SFR	DOM	SD	CA	c1940	1	CP	SE-1	N	WF	WC	N	CL	G	A	N	OR	INT	INT	N	na	INT	Y	N
55.20-1-12	155	WASHINGTON AVE	SI	EDU	EDU	SCH	na	1933	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	Y	N
68.5-4-2	404	WEST MAIN ST	B	MFR	DOM	MD	IT	c1870	2	O	N	N	WF	WC	VS part	CL	H	SSM	N	N	INT	REP	FE	ALT	INT	Y	Y
68.5-2-31	409	WEST MAIN ST	B	MFR	DOM	SD	IT	c1870	2	O	SE-2 & RE-2	N	WF	WC	MS	CL	H	A	N	N	ALT	REP	FWS	REP	ALT	Y	Y
68.5-4-3	410	WEST MAIN ST	B	MFR	DOM	MD	IT	c1870	2	O	N	H	WF	WC	MS	CL	H	SSM	N	N	INT	INT	FE	ALT	INT	Y	N
68.5-2-30	413	WEST MAIN ST	B	MFR	DOM	SD	IT	c1870	2	UPW	SE-2	H	WF	WC	N	CL	FG	O	N	N	ALT	REP	FF	INT	INT	Y	Y

Description of decorative features & Notes	ACCESSORY STRUCTURES							Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan	Description		
Front porch has pedimented gable roof, Doric columns; door surround; paneled front door; clean lines, orig. materials; 6-over-1 windows with Craftsman-type muntin pattern; not on 1904 Sanborn; 1927 Sanborn shows present footprint	G	Y	N	INT	Y	N	WF; WS; c1920 single stall garage (on 1927 Sanborn map); o.h. door installed	Unique garden gate w/multiple pickets w/curved detail	
Projecting pedimented front entrance pavilion w/fluted pilasters; 6-over-1 sash windows w/blinds; tuck under garage w/small balcony above; not on 1927 Sanborn map	N							Extensive bluestone retaining walls & walkways	
This open space is a part of the larger tract of land owned by the School District and provides an approach to the 1933 school further north up a hill; a concrete sidewalk is centered on the site, leading from the sidewalk along the north side of Elm up to concrete steps going up the hill, w/coniferous trees and light posts on either side	N								
Wide cornices w/decor. double brackets; window & door surrounds; central chimney intact; appears on 1883 Birdseye; blt as duplex; NOTE: missing fascia on overhanging eave (east side) endangered by lack of maintenance & hard use as student housing	N								
Bldg has been stripped of all its orig. decor. elements (except for columns on rear porch); porch has been altered; remains contributing because of Italianate form is still evident; appears on 1883 Birdseye; endangered by lack of maintenance & insensitive alterations	N								
Wide cornice w/decor. double brackets; central window header w/pediment; window & door surrounds; pedimented front porch w/Doric columns; central chimney intact; appears on 1883 Birdseye	N								
Window surrounds w/dentils; wide cornice; ornate decor. elements on porch; fiese w/pendants; scroll sawn braces; appears on 1883 Birdseye; NOTE: missing double brackets @ cornice; front porch in very poor condition w/railing & skirting missing; roof appears to be patched (tarred & painted?) thus endangered due to very poor maintenance	G	N	N	INT	N	N	WF; WC; 2-stall 1-story front gable garage w/o.h. door, c1960	Cut limestone retaining wall along front property line w/bluestone cap; bluestone walkways	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-4-4	414	WEST MAIN ST	B	SFR	DOM	SD	IT	c1870	2	UPW	SE-2	H	WF	WC	N	CL-CP & S	FG	S	N	N	INT	REP	FE	ALT	ALT	Y	N
68.5-2-28	419	WEST MAIN ST	B	MFR	DOM	MD	IT	c1870	2	O	SE-2 & RE-2	H	WF	WC	N	CL	H	SSM	N	N	INT	INT	FF	INT	INT	Y	N
68.5-4-5	420	WEST MAIN ST	B	MFR	DOM	MD	GO	c1870	2	UPW	SE-2	H	WF	WC	N	CL	FG	SSM	Y	OR	INT	REP	FWS	REP	ALT	Y	N
68.5-2-27	425	WEST MAIN ST	B	SFR	DOM	SD	QA	c1890	2	O	N	N	M	B & WS	N	CL	H	A	Y	N	INT	INT	FWS	INT	INT	Y	N
68.5-4-6	426	WEST MAIN ST	B	MFR	DOM	SD	GR	c1870	2	SP	SE	H	WF	WC	N	CL	FG	SSM	Y	N	INT	INT	S	ENC	INT	Y	N
68.5-2-26	429	WEST MAIN ST	B	SFR	DOM	SD	CC	c1915	1-1/2	O	N	N	WF	WC	N	CL	FG	A	N	OR	INT	INT	FF	INT	INT	Y	N
68.5-4-7	430	WEST MAIN ST	B	SFR	DOM	SD	A4	c1910	2	O	RE-1	N	WF	WC	N	CL	H	S	N	OR	INT	INT	FF & S	INT & REP	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Window & door surrounds; 2-story box bay on east side; paneling under windows; wide cornice still remains on side ell; appears on 1883 Birdseye; 1-story rear lean-to prob. dates to late 19th century; NOTES: front gable end has been altered (decor. elements/shingling removed, attic window alt.); front entrance porch has been altered w/all decor. elements removed; siding has been extended down over foundation w/concrete parging in other sections	B	Y	N	INT	Y	N	WF; WC; c1870; hay door intact; garage doors altered	
Appears to have been blt. as duplex; intact double doors; unique porch w/curved roof, scroll sawn skirting & rectilinear braces, turned columns; rear porch probably added before 1900; appears on 1883 Birdseye view; NOTE: brackets missing on wide cornice	B	Y	N	INT	Y	Y	Wonderfully intact c1870 barn; hay door; attic window; multi-paned colored glass window in garage door; endangered because open to elements	
Window & door surrounds; turned columns, spindled frieze, & scroll sawn braces on porch; decor. verge board; dormer w/multipaned & colored glass; NOTE: board & batten decor. on side gable ends reveal orig. style was Gothic Revival; front gable was redone w/fish scale shingles	N							
Tower w/conical roof; roof is asphalt w/copper metal edging; decor. shingles on gable ends & tower; front & side bays w/bracketed projecting gables, braces w/pendants beneath; side canopy w/decor. brackets; 3 & 4 header courses over doors & windows; arched windows; limestone detailing on windows; wrap-around porch w/scroll sawn skirting; NOTE: 2 windows on west side filled in w/brick	B	Y	N	INT	Y	N	WF; WC; c1890 barn w/hip roof, broken eave dormer w/multipaned colored glass window; o.h. door installed	Bluestone walkways
Simple Greek Revival w/shutters; rear door canopy; side porch probably enclosed early; appears on 1883 Birdseye	B	Y	N	INT	Y	N	WF; WC; gable SSM roof c1870 barn w/orig. sliding doors & hay door intact	
Brick piers on porch w/matching chimney; box bay on west side; Jerkin head on front gable & side dormer; extended & carved ceiling joists on front porch; exposed & decor. rafters	G	Y	N	INT	Y	N	Small 1-stall c1915 garage that closely matches Craftsman Cottage style of house w/Jerkin head front gable & brick piers; o.h. door installed	
Classical details applied to Am. 4-Square; pediment over front porch entrance & Doric columns; oval stained glass window on west façade; 2-story bay window on west façade w/curved metal roof; dormers w/arched windows; window & door surrounds; 1-story rear ell likely original; first appears on 1927 Sanborn map	G	Y	N	INT	Y	N	1-story c1910 garage; WF; WN; hip roof w/slate shingles; multi-paned dormer window; sliding doors intact; multi-paned windows in gar. doors	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-2-25	435	WEST MAIN ST	B	SFR	DOM	SD	GR	c1860	2	CP	RE-2	H	WF	WC	N	CL - C	G	S	N	N	INT	INT	FE & S & R	INT	INT	Y	N
68.5-4-8	436	WEST MAIN ST	B	C	DOM	MD	QA	c1890	2	O	N	NH	WF	WC	N	CL	H	S	Y	N	INT	INT	FWS	INT	INT	Y	N
68.5-4-9	440	WEST MAIN ST	B	C	DOM	SD	QA	c1890	2	O	N	N	WF	B & WS	N	CL	H	S	N	OR	REP	REP	FE	ALT	INT	Y	N
68.5-2-24	443	WEST MAIN ST	B	MFR	DOM	SD	IT	c1870	2	SP	RE-2	N	WF	WC	VS	CL	H	SSM	N	N	INT	INT	FE & R	INT	INT	Y	N
68.5-4-16	450	WEST MAIN ST	B	MFR	DOM	MD	QA	c1890	2	O	RE-1	N	WF	WC	COM	CL	H	S	Y	OR	INT	REP	FE	REP	INT	Y	N
68.5-3-37	451	WEST MAIN ST	B	SOC/ HAL	REL	CH	ROM	1886	na	na	na	N	M	B	N	CL	FG	S	N	N	INT	INT	FE	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
An early Federal house (c1850? may be on 1866 map) w/seams in corner pilasters--evidence of being raised from 1-1/2 stories to 2 stories by 1883 (on Birdseye); Greek Revival treatment gives c1860 date; rear enlargements made between 1904 & 1927 (per Sanborn maps); door surround w/transom & multi-paned sidelights; false windows w/blinds on 2nd fl.; window surrounds; wide cornice & corner boards	B	Y	N	ALT	Y	N	Small 1-story barn w/attic c1860; WF; WN; gable roof w/slate shingles matches house; NOTE: has been converted to residence	Bluestone walkways
Blt as duplex; door & window surrounds; spindled frieze on porch w/scroll sawn panels, brackets & skirting; turned columns; multi-paned colored glass attic windows; not on 1883 Birdseye, appears on 1904 Sanborn; rear ell addition post 1927 (per Sanborn)	B	Y	N	INT	Y	N	WF; WC c1890 barn; doors, hay door, & windows intact	
Bed & Breakfast Inn; front wrap-around porch was removed some time after 1927 (per Sanborn map); not on 1883 Birdseye, on 1904 Sanborn; 2 different stone types in foundation; multi-paned colored glass windows on 2nd fl. & Venetian attic window; limestone lintels & ornamented headers on windows; arched windows w/decor. brickwork; dentiled pedements on gable ends & dormer; decor. shingle treatment on gable ends & dormer; 2-story bay on east side	B	Y	Y	ALT	Y	N	Large 2-story c 1890 barn; WF; WC & WS; slate roof w/metal edge; cupola w/finial; multi-paned colored glass window; NOTE: Converted to residence	
Paneled doors; pediment, brackets & dentils on front porch; decor. bracketed cornice; 2 1-story bay windows on west side; 2-story bay w/brackets & ornament. on east side; on 1883 Birdseye; 1904 & 1927 Sanborns show house w/ a wrap-around porch (south & east sides) + rear & side porches	B	Y	N	ALT	Y	N	WF; WC & WS c1870 2-story barn; door & window w/multipaned colored glass intact; vinyl siding on lower portion	
Paneled banding between 2nd fl. & attic; false front on rear ell; brackets w/pendants on 2nd story bay windows (both east & west facades); multi-paned colored glass attic window on west side; rear lean-to has decor. exposed brackets; 1904 Sanborn illustrates duplex; NOTE: Attic windows replaced w/vents; handicapped access ramp to front porch along west side	G	N	N	ALT	Y	N	1-story WF; WC; 2-stall garage w/1 sliding door & 1 set of swing doors; flat SSM roof	
Former Dutch Reformed Church; square tower w/Greek Temple front; Romanesque arched windows; oval window w/nuntines @ front gable end; bracketed eave on tower; small corner apse projection off NE corner; date plaque on bldg states 1919 (when Masons got bldg); [property not shown on 1887 Sanborn]; on 1904 Sanborn	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-4-17	454	WEST MAIN ST	B	MFR	DOM	SD	U	c1900	2	O	RE-1-1/2 & 1	N	WF	WC	VS	CL	FG	N	N	N	REP	INT	FE	REP	ALT	Y	N
68.5-3-36	457	WEST MAIN ST	B	SFR	DOM	SD	QA	c1890	2	O	N	N	WF	WC & BB	N	CL	H	A	Y	N	INT	INT	FF	INT	INT	Y	N
68.5-4-18	458	WEST MAIN ST	B	SFR	DOM	SD	QA	c1890	2	O	RE-1-1/2	H & NH	WF	WC	N	CL	H or CG	SSM	N	N	INT	INT	FF	INT	INT	Y	N
68.5-3-69	461 - 463	WEST MAIN ST	B	MFR	DOM	MD	QA	c1890	2	O	N	N	WF	WC	N	CL	H	SSM	Y	N	INT	INT	FWS	INT	INT	Y	N
68.5-4-19	460	WEST MAIN ST	B	MFR	DOM	SD	IT	c1900	2	O	RE-2	NH	WF	WC	N	CL	H	SSM	N	N	INT	REP	FF	REP	INT	Y	Y
68.5-3-35	467	WEST MAIN ST	B	MFR	DOM	SD	IT	c1870	2	O	SE-2	N	WF	WC	N	CL	H	A & SSM	N	N	INT	INT	FF	REP	INT	Y	N
68.5-4-20	468	WEST MAIN ST	B	SFR	DOM	SD	IT	c1870	2	SP	RE-1	N	WF	WC	N	CL	H	SSM	N	N	INT	INT	FF	INT	INT	Y	Y
68.5-4-21	470	WEST MAIN ST	B	MFR	DOM	SD	IT	c1900	2	SP	RE-2	N	WF	WC	N	CL	FL	SSM	N	N	INT	INT	FWS	INT	INT	Y	Y

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Turned pilaster on 1 side of front door; 1 scroll sawn bracket on front entrance porch; on 1904 Sanborn map; not on 1883 Birdseye; NOTE: any original decor. details has been removed or covered over w/vinyl siding; side porch removed	B	?	N	ALT	Y	N	WF; WC 2-story barn may predate house (1883 Birdseye shows extensive outbldgs) has been converted to Day Care center & connected to barn next door to east	Bluestone walkways
Full front porch w/Doric columns, scroll sawn railing & skirting; banding; board & batten on gable ends; 1-story box bay on west side; 2-story bay window on east side w/bracketed projecting gable roof; exposed decor. rafters; decor. verge board; multi-paned colored glass attic window & 1st fl. window on west side; not on 1883 Birdseye; on 1904 Sanborn	B	N	N	INT	Y	N	WF, WC gambrel roof barn w/sliding doors intact (could be earlier than house - appears to be on 1883 Birdseye)	
Highly decorated w/stick work; board & batten banding betw. 1st & 2nd floors; various shingles & applied moldings; exposed rafters; bracketed cornice; decor. gable ends w/board & batten; porch w/pediment over entrance, turned columns, intact railing & scroll sawn skirting brackets & braces; glazed front entrance vestibule; 2-story bay window w/bracketed corners	B	Y	Y	ALT	Y	N	WF, WC c1890; connected to next door accessory bldg [see notes on 454 W. Main St.]	
Blt as duplex; window & door surrounds; front porch w/scroll sawn brackets, braces, railing & skirting & turned columns, hexagonal shape; cut corners on front provide bay effect w/large decor. brackets at angled 2nd fl. windows multi-paned colored glass attic window; doesn't seem to be on 1883 Birdseye; on 1904 Sanborn	B	Y	N	ALT	Y	N	WF; WC gable barn; o.h. doors installed; SSM roof	
Earliest bldg appears is on 1904 Sanborn map; has been stripped o all arch details (probably had brackets) Endangered by poor maintenance	B	N	N	INT	Y	N	WF; WN; front gable, c1915 barn w/doors & windows intact	
Door & window surrounds; appears to be on 1883 Birdseye; NOTE: brackets have been removed	B	Y	N	INT	Y	N	WF, WC c1870 hay door & sliding doors intact	
Double-bracketed cornice; scroll sawn braces on front portch; 1-story bay window on west side; on 1883 Birdseye & 1887 Sanborn map; NOTE: bldg endangered by being vacant (neighbors say 3-4 years vacant)	B	Y	N	ALT	Y	Y	WF; WC; C1870; o. h. doors installed; hay door intact	
Double bracketed cornice w/overhanging eave; scroll sawn braces & brackets on front porch; false front parapet wall in front of rear ell (hides gable roof); 1-over-1 windows makes this a later Italianate; earliest map it shows up on is 1904 Sanborn; NOTE: endangered because of poor maintenance & hard use by multiple tenants	B	Y	N	INT	Y	N	WF, WN sliding door & hay door intact; in better condition than house	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-34	473	WEST MAIN ST	B	C & R	DOM	SD	GR	c1850	2	UPW	RE	H	WF	WC	COM	CL	CG	SSM	N	N	MIX	REP	FF	INT	INT	Y	N
68.5-4-22	478	WEST MAIN ST	B	C	DOM	SD	BIGB	c1980	1	O	N	N	SF	MS	N	C	FL	U	N	N	INT	INT	N	na	INT	N	N
68.5-3-33	479	WEST MAIN ST	B	C & R	DOM	SD	GR	c1850	2	UPW	RE-2	H	WF	WC	VS	CL	CG	SSM	N	N	INT	INT	F & S	REP	ALT	Y	N
68.5-3-32	483	WEST MAIN ST	B	REL	DOM	SD	U	c1850	2	UPW	RE-2	H & NH	WF	WC	MS	CL	CG	A	Y	N	MIX	ALT	F	REM	ALT	Y	N
68.5-3-31	489	WEST MAIN ST	B	REL	DOM	SD	A4	c1910	2	SQ	N	N	WF	WC	VS	CL	H	A	N	OR	MIX	REP	FE	ALT	INT	Y	N
68.5-4-23	492	WEST MAIN ST	B	REL	REL	CH	SH	1887	na	na	na	NH	WF	WS	ASB	CL	CG	A	Y	N	INT	REP	na	na	ALT	Y	N
68.5-3-30	493	WEST MAIN ST	B	SFR	DOM	SD	IT	c1870	2	SP	RE	N	WF	WC	N	CL	H	SSM	N	OR	INT	REP	FF	INT	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Window & door surrounds; wide cornice; highly decor. front porch w/scroll sawn brackets, braces, railing, panels on skirting, & turned columns; bow window w/transoms on 1st fl. under porch roof; possibly shown on 1866 map; on 1883 Birdseye; porch extended across full front of house between 1892 & 1904 per Sanborn maps; 2nd stories added to side & rear ells after 1883/1887; NOTE: now used as office for Leon Wilson Realty; rear 2nd story porch & enclosed exterior stairway to 2nd fl. added in mid-20th century	G	N			N		mid- to late-20th century double garage replaced a 2 story barn	
Advance Auto Parts & Schoharie County Office of Aging: large pole bldg c1970	N							
Wide cornice; porch w/scroll sawn skirting & Doric columns, partially glazed; on 1883 Birdseye, poss. 1866 map; front porch extended to present configuration between 1887 & 1892 per Sanborn maps; NOTE: architectural details have been lost or covered over w/vinyl siding	B	Y	N	INT	Y	N	WF; WC; false front on gable roof; sliding doors & hay door intact; small cupola added w/wind odometer	Small replica of Dutch windmill in back yard
DGEVS on west side gable over 2-story bay; on 1883 Birdseye, 1887 & 1892 Sanborn maps; west side bay window added by 1904 (Sanborn); NOTE: Remodeled in late 20th century to house the Christian Science Society Determined intact because of form, scale, side & rear portions of the house remain as built & front of house could be restored	SH						WF; WN intact except now attached to the rear of the building	
Classical Revival details; sidelights on front door; front attic dormer has Venetian window w/ keystone arch; diamond patterned muntins in upper portion of 2nd floor windows; other patterned muntins elsewhere; orig. large flared chimney; shows up 1st on 1927 Sanborn map	B	N	N	ALT	Y	N	WF; WC large 2-story barn which probably predates house--c1880; slate hip roof w/projecting gable & broken eave dormer; shows up on 1887 Sanborn (2 story w/1-story ell on east); 1904 labels barn as "Wagon House"; 1927 Sanborn labels barn as "Concrete Casket Mfg."	
Square bell tower; Craftsman stained glass in windows w/lancet arches; decorative gable end projections (DGEVS) w/brackets; historic photo shows that orig. siding was wood shingles NOTE: front entrance foyer addition & side ell (school/office addition) date to late 20th century	N							
Sidelights & transom on door; large 2-part cornice; decor. brackets & braces on front porch; on 1883 Birdseye & 1887 Sanborn map	G	N	N	INT	Y	N	WF; WC small 1-stall garage; c1930; Jerkin head front gable roof	

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-28	503	WEST MAIN ST	B	C	IND	MFG	CR	c1880	2	O	RE	H	M	B	N	CL	FL	U	N	na	MIX	REP	na	na	ALT	Y	N
68.5-3-26	509	WEST MAIN ST	B	C & REL	IND	MFG	U	c1900	2	O	N	N	WF	U	STU & BB	U	CG	A	N	A	ALT	ALT	na	na	ALT	Y	N
68.5-3-26	513	WEST MAIN ST	B	C	C/T	WHS	U	c1904	1	O	NH	H & NH	M & WF	U	STU & BB	U	M	A	N	N	ALT	INT	na	na	ALT	Y	N
68.5-3-25	521	WEST MAIN ST	B	C	DOM	HOT	U	c1870	1	UPW	RE (2)	H	WF	WC	N	CL	G	U	N	N	ALT	ALT	FF	ALT	ALT	Y	N
68.5-3-24	523	WEST MAIN ST	B	C	C/T	SPE	IT	c1880	2	O	RE-2	N	WF & M	B	N	B	CG	SSM	N	N	MIX	REP	FF	ENC	INT	Y	N

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
Early Industrial bldg built next to Mill Creek; dentiled brickwork along roof line; arched windows & doorways; rear 1-story garage ell blt. of concrete block connects to WF 2-story bldg. along back of property fronting on Mill Creek Lane; on 1883 Birdseye, 1887 Sanborn: "E. Waldron Foundary & Mach. Shop"; 1892 Sanborn: "C Hallenbeck Carriage Fac."; 1904 Sanborn: "Carriage Reposy"; 1927 Sanborn "Auto Reppg. & Farm Tractors"; NOTE: bldg. has been sandblasted; current business, Hawgs Breath Cycles	N							
First appears on 1904 Sanborn as a 2-story barn for a dwelling that was demolished; 1927 Sanborn identifies this bldg as a "Tin Smith"	N							
Ogee arched front doors now obscured by brick piers on front of bldg; orig car storage/ dealership; 1904 Sanborn shows 1-story masonry/brick bldg at rear of lot (massive chimney intact) & labeled "Storage"; 1927 Sanborn shows rear portion as Auto Stge. (a narrower bldg--dwelling & store--was since demolished) also a separated dwelling/store to west on property (since demolished); NOTE: mansard roof & brick recladding dates to mid-20th century; current business: Speedling Florist	N							
Dentiled cornice on porch; 1883 Birdseye shows 2-story gable roof structure w/front porch; 1887 Sanborn shows same footprint labeled "Benedict House"; 1892 Sanborn, "Exchange Hotel"; 1904 Sanborn, "Exchange Hotel" & "Bar" on rear ell; 1927 Sanborn, store & "Battery Station"; 1st rear ell added after 1892; aka "Park Hotel"; NOTE: Bldg burned in 1996;lean-to on side ell added later; 2-story false front was added in 2003; concrete block infill/porch & brick piers later; was under construction after fire at time of 2003 survey	N							
Bracketed cornice on false front w/gable roof behind; 2nd story bow window; decor. brick headers on wnd story window; cornice frieze has been stuccoed; enclosed exterior stairway to 2nd floor (on 1927 Sanborn) has been removed shadow is evident on east facade; on 1883 Birdseye; 1887 Sanborn, "Gro."; 1892 Sanborn "Gro." w/rear ell removed; 1904 Sanborn shows brick facade around entire bldg w/small rear wing, "Gro.", "Wall Paper" & "Ven'd", also that 1st floor front is open (porch as shown in previous year footprints) NOTE: Appears to have been sandblasted	N							

Cobleskill Historic District - Historic Resource Inventory

PRIMARY STRUCTURE																											
SBL	Street #	Street/Location	Type	Use	Hist Use	Sub-categ	Style	Date	Stories	Plan Type	Wings	Add	Const Meth	Siding	Resid?	Found	Roof Type	Roof Mat	dgevs	Dorm	Wind	Door	Porch Loca	Porch Cond	Over all Integ	Contr	Endan
68.5-3-23	529	WEST MAIN ST	B	C	GOV	FIR	IT	c1880	2	O	RE-1	H	WF	WC	N	CL	FL	U	N	N	INT	ALT	na	na	INT	Y	N
68.5-5-1	PARK	WEST MAIN ST	SI & ST	REC	R/C	REC	na	1914	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	na	INT	Y	N
ROW	-	WEST MAIN ST	ST	BRI	TRA	RD	ARTD	U	na	na	n	n	na	na	na	na	na	na	na	na	na	na	na	INT	Y	N	

Description of decorative features & Notes	ACCESSORY STRUCTURES						Description & Notes	LANDSCAPE FEATURES
	Type	Match	dgevs	Integ	Contrib	Endan		Description
False front w/bracketed cornice, scroll sawn moldings, gable detail w/decor. verge board, & corner pilasters; ornate window headers; pedimented pentice w/cornice betw. 1st & 2nd fl.; paneled corner boards; on 1883 Birdseye; 1887 Sanborn, "Engine House" & "Jail"; 1892 Sanborn "Fire Eng. House" & "Lock Up"; 1904 "Fire Hose Ho."; 1927 Sanborn, "Fire Dept." & "Lock Up"; exterior enclosed stairway added after 1927; 2nd fl. windows intact; NOTE: 1st fl. garage doors infilled w/windows & doors;	N							
1.3 acre Center Park on the site of former industrial and commercial complex around orig. Mill Pond; current structures include: curved creek channel walls of bluestone, bridge over mill pond/creek/spillway w/iron handrails & structural elements, wood decking; concrete & bluestone bulkhead around pond; wood frame octagonal gazebo w/asphalt shingles; granite, polished granite Veterans memorial w/inscription: "Dedicated to the memory of ALL Veterans Living & Deceased who served their country in all wars"; Cannon; Memoriam statue "In Memory of Willis Goss MacDonald MD LLD 1862-1910, 4-sided clock @ corner of Main & Grand, cast iron historic plaque, 2 raised octagonal planters w/cobblestone facing & concrete coping; 6 park benches; 7 trash receptacles; lantern light fixture; railroad tie planter box; landscaping is naturalistic w/a variety of coniferous & deciduous specimin trees including spruce, maple, crabapple & ash NOTE: 1914 Cobblestone bandstand structure was demolished in 1952	O						As noted under main description	
Cast concrete Art Moderne bridge over Mill Creek at 500 block of West Main St.	N							